



OM-265363S

2023-12

Processes



Submerged Arc (SAW) Welding
Electroslag (ESW) Welding



Air Carbon Arc (CAC-A) Cutting
and Gouging



Description



Arc Welding Power Source

SubArc DC 650,1000 DC 800 CE, 1250 CE

Digital Power Sources



For product information,
Owner's Manual translations,
and more, visit

www.MillerWelds.com

OWNER'S MANUAL

From Miller to You

Thank you and congratulations on choosing Miller. Now you can get the job done and get it done right. We know you don't have time to do it any other way.

That's why when Niels Miller first started building arc welders in 1929, he made sure his products offered long-lasting value and superior quality. Like you, his customers couldn't afford anything less. Miller products had to be more than the best they could be. They had to be the best you could buy.

Today, the people that build and sell Miller products continue the tradition. They're just as committed to providing equipment and service that meets the high standards of quality and value established in 1929.

This Owner's Manual is designed to help you get the most out of your Miller products. Please take time to read the Safety Precautions. They will help you protect yourself against potential hazards on the worksite. We've made installation and operation quick and easy. With Miller, you can count on years of reliable service with proper maintenance. And if for some reason the unit needs repair, there's a Troubleshooting section that will help you figure out what the problem is, and our extensive service network is there to help fix the problem. Warranty and maintenance information for your particular model are also provided.

Miller Electric manufactures a full line of welders and welding-related equipment. For information on other quality Miller products, contact your local Miller distributor to receive the latest full line catalog or individual specification sheets. **To locate your nearest distributor or service agency call**

1-800-4-A-Miller, or visit us at www.MillerWelds.com on the web.



Working as hard as you do – every power source from Miller is backed by the most hassle-free warranty in the business.



ISO 9001
Quality

Miller is the first welding equipment manufacturer in the U.S.A. to be registered to the ISO 9001 Quality System Standard.



TABLE OF CONTENTS

SECTION 1 – SAFETY PRECAUTIONS – READ BEFORE USING	1
1-1 Symbol Usage	1
1-2 Arc Welding Hazards	1
1-3 Additional Hazards For Installation, Operation, And Maintenance	3
1-4 California Proposition 65 Warnings	4
1-5 Principal Safety Standards	4
1-6 EMF Information	4
SECTION 2 – CONSIGNES DE SÉCURITÉ - LIRE AVANT UTILISATION	5
2-1 Symboles utilisés	5
2-2 Dangers relatifs au soudage à l'arc	5
2-3 Symboles de dangers supplémentaires en relation avec l'installation, le fonctionnement et la maintenance	7
2-4 Proposition californienne 65 Avertissements	9
2-5 Principales normes de sécurité	9
2-6 Informations relatives aux CEM	9
SECTION 3 – DEFINITIONS	10
3-1 Additional Safety Symbol Definitions	10
3-2 Miscellaneous Symbol Definitions	13
SECTION 4 – SPECIFICATIONS	14
4-1 Serial Number And Rating Label Location	14
4-2 Software Licensing Agreement	14
4-3 Information About Default Weld Parameters And Settings	14
4-4 Specifications	14
4-5 SubArc System Compatibility	15
4-6 Static Characteristics	15
4-7 Environmental Specifications	15
4-8 Duty Cycle And Overheating	17
SECTION 5 – INSTALLATION	19
5-1 Dimensions And Weights	19
5-2 Selecting A Location	20
5-3 Typical Equipment Location	20
5-4 Electrical Service Guide	21
5-5 Placing Jumper Links	23
5-6 Connecting 3-Phase Input Power For DC 650/800 Models	24
5-7 Connecting 3-Phase Input Power For DC 650/800 Models (Continued)	25
5-8 Connecting 3-Phase Input Power For DC 1000/1250 Models	26
5-9 Connecting 3-Phase Input Power For DC 1000/1250 Models (Continued)	27
SECTION 6 – SYSTEM CONNECTIONS	28
6-1 Terminal Strip TE2 and Receptacle RC1 Information	28
6-2 Terminal Strip TE1	29
SECTION 7 – MAKING WELD OUTPUT CONNECTIONS	30
7-1 Weld Output Terminals And Selecting Cables Sizes*	30
7-2 Weld Output Terminals	31
7-3 Connecting Weld Output Cables	31
7-4 Basic SubArc (SAW) Welding	32
7-5 Typical Connection For CAC-A Process	36
7-6 Connecting Multiple Units	37
SECTION 8 – POWER SOURCE OPERATION	38
8-1 Controls	38
SECTION 9 – PLC OPERATION	39
9-1 Automation Interface Hardware Configuration (PLC Users Only)	39
9-2 Connection To PLC	39
9-3 Example Power Source Operation Using A PLC	40
SECTION 10 – MAINTENANCE AND TROUBLESHOOTING	43
10-1 SubArc System Help Codes	43
10-2 Routine Maintenance	46
10-3 Fuse F1	46
10-4 Troubleshooting Table	47
SECTION 11 – ELECTRICAL DIAGRAMS	48

DECLARATION OF CONFORMITY



for European Community (CE marked) products.

MILLER Electric Mfg. LLC, 1635 West Spencer Street, Appleton, WI 54914 U.S.A. declares that the product(s) identified in this declaration conform to the essential requirements and provisions of the stated Council Directive(s), Commission Regulation(s) and Standard(s).

Product/Apparatus Identification:

Product	Stock Number
Subarc DC 800 Digital 50/60HZ CE	907623
Subarc DC 1250 Digital 50/60HZ CE	907625

Council Directives and Commission Regulations:

- 2014/35/EU Low voltage
- 2014/30/EU Electromagnetic compatibility
- 2011/65/EU and amendment 2015/863 Restriction of the use of certain hazardous substances in electrical and electronic equipment

Standards:

- EN IEC 60974-1:2018/A1:2019 Arc welding equipment – Part 1: Welding power sources
- EN 60974-10:2014/A1:2015 Arc welding equipment – Part 10: Electromagnetic compatibility requirements
- EN IEC 63000:2018 – Technical documentation for the assessment of electrical and electronic products with respect to the restriction of hazardous substances

Signatory:

June 15, 2021

David A. Werba
MANAGER, PRODUCT DESIGN COMPLIANCE

Date of Declaration

266179D



DECLARATION OF CONFORMITY

For United Kingdom (UKCA marked) products.

MILLER Electric Mfg. LLC, 1635 West Spencer Street, Appleton, WI 54914 U.S.A. declares that the product(s) identified in this declaration conform to the essential requirements and provisions of the stated Regulation(s) and Standard(s).

Product/Apparatus Identification:

Product	Stock Number
Subarc DC 800 Digital 50/60HZ CE	907623
Subarc DC 1250 Digital 50/60HZ CE	907625

Regulations:

- S.I. 2016/1101 Electrical Equipment (Safety) Regulations 2016
- S.I. 2016/1091 Electromagnetic Compatibility Regulations 2016
- S.I. 2012/3032 Restriction of the Use of Certain Hazardous Substances in Electrical and Electronic Equipment Regulations 2012

Standards:

- EN IEC 60974-1:2018/A1:2019 Arc welding equipment – Part 1 Welding power sources
- EN 60974-10:2014/A1:2015 Arc welding equipment – Part 10: Electromagnetic compatibility requirements
- EN IEC 63000:2018 Technical documentation for the assessment of electrical and electronic products with respect to the restriction of hazardous substances

Signatory:

June 15, 2021

David A. Werba
MANAGER, PRODUCT DESIGN COMPLIANCE

Date of Declaration

290465A

EMF DATA SHEET FOR ARC WELDING POWER SOURCE



Product/Apparatus Identification

Product	Stock Number
SUBARC DC 1250 DIGITAL	907625
SUBARC DC 1000 DIGITAL	907624
SUBARC DC 800 DIGITAL	907623
SUBARC DC 650 DIGITAL	907622

Compliance Information Summary

Applicable regulation Directive 2014/35/EU

Reference limits Directive 2013/35/EU, Recommendation 1999/519/EC

Applicable standards IEC 62822-1:2016, IEC 62822-2:2016

Intended use for occupational use for use by laymen

Non-thermal effects need to be considered for workplace assessment YES NO

Thermal effects need to be considered for workplace assessment YES NO

Data is based on maximum power source capability (valid unless firmware/hardware is changed)

Data is based on worst case setting/program (only valid until setting options/welding programs are changed)

Data is based on multiple settings/programs (only valid until setting options/welding programs are changed)

Occupational exposure is below the Exposure Limit Values (ELVs) for health effects at the standardized configurations YES NO
(if NO, specific required minimum distances apply)

Occupational exposure is below the Exposure Limit Values (ELVs) for sensory effects at the standardized configurations n.a YES NO
(if applicable and NO, specific measures are needed)

Occupational exposure is below the Action Levels (ALs) at the standardized configurations n.a YES NO
(if applicable and NO, specific signage is needed)

EMF Data for Non-thermal Effects

Exposure Indices (EIs) and distances to welding circuit (for each operation mode, as applicable)

	Head		Trunk	Limb (hand)	Limb (thigh)
	Sensory Effects	Health Effects			
Standardized distance	10 cm	10 cm	10 cm	3 cm	3 cm
ELV EI @ standardized distance	0.19	0.04	0.07	0.04	0.08
Required minimum distance	1 cm	1 cm	1 cm	1 cm	1 cm

Distance where all occupational ELV Exposure Indices fall below 0.20 (20%) 10 cm

Distance where all general public ELV Exposure Indices fall below 1.00 (100%) 72 cm


Tested by: Tony Samimi Date tested: 2016-03-01


275579-A

SECTION 1 – SAFETY PRECAUTIONS – READ BEFORE USING

 Protect yourself and others from injury—read, follow, and save these important safety precautions and operating instructions.

1-1. Symbol Usage

 **DANGER!** – Indicates a hazardous situation which, if not avoided, will result in death or serious injury. The possible hazards are shown in the adjoining symbols or explained in the text.

 Indicates a hazardous situation which, if not avoided, could result in death or serious injury. The possible hazards are shown in the adjoining symbols or explained in the text.


NOTICE – Indicates statements not related to personal injury.


 Indicates special instructions.




This group of symbols means Warning! Watch Out! ELECTRIC SHOCK, MOVING PARTS, and HOT PARTS hazards. Consult symbols and related instructions below for necessary actions to avoid these hazards.

1-2. Arc Welding Hazards

 The symbols shown below are used throughout this manual to call attention to and identify possible hazards. When you see the symbol, watch out, and follow the related instructions to avoid the hazard. The safety information given below is only a summary of the more complete safety information found in the Principal Safety Standards. Read and follow all Safety Standards.

 Only qualified persons should install, operate, maintain, and repair this equipment. A qualified person is defined as one who, by possession of a recognized degree, certificate, or professional standing, or who by extensive knowledge, training and experience, has successfully demonstrated the ability to solve or resolve problems relating to the subject matter, the work, or the project and has received safety training to recognize and avoid the hazards involved.

 During operation, keep everybody, especially children, away.



ELECTRIC SHOCK can kill.

Touching live electrical parts can cause fatal shocks or severe burns. The electrode and work circuit is electrically live whenever the output is on.

The input power circuit and machine internal circuits are also live when power is on. In semiautomatic or automatic wire welding, the wire, wire reel, drive roll housing, and all metal parts touching the welding wire are electrically live. Incorrectly installed or improperly grounded equipment is a hazard.

- Do not touch live electrical parts.
- Wear dry, hole-free insulating gloves and body protection.
- Insulate yourself from work and ground using dry insulating mats or covers big enough to prevent any physical contact with the work or ground.
- Do not use AC weld output in damp, wet, or confined spaces, or if there is a danger of falling.
- Use AC output ONLY if required for the welding process.
- If AC output is required, use remote output control if present on unit.
- Additional safety precautions are required when any of the following electrically hazardous conditions are present: in damp locations or while wearing wet clothing; on metal structures such as floors, gratings, or scaffolds; when in cramped positions such as sitting, kneeling, or lying; or when there is a high risk of unavoidable or accidental contact with the workpiece or ground. For these conditions, use the following equipment in order presented: 1) a semiautomatic DC constant voltage (wire) welder, 2) a DC manual

(stick) welder, or 3) an AC welder with reduced open-circuit voltage. In most situations, use of a DC, constant voltage wire welder is recommended. And, do not work alone!


- Disconnect input power or stop engine before installing or servicing this equipment. Lockout/tagout input power according to OSHA 29 CFR 1910.147 (see Safety Standards).
- Properly install, ground, and operate this equipment according to its Owner's Manual and national, state, and local codes.
- Always verify the supply ground—check and be sure that input power cord ground wire is properly connected to ground terminal in disconnect box or that cord plug is connected to a properly grounded receptacle outlet.
- When making input connections, attach proper grounding conductor first—double-check connections.
- Keep cords dry, free of oil and grease, and protected from hot metal and sparks.
- Frequently inspect input power cord and ground conductor for damage or bare wiring—replace immediately if damaged—bare wiring can kill.
- Turn off all equipment when not in use.
- Do not use worn, damaged, undersized, or repaired cables.
- Do not drape cables over your body.
- If earth grounding of the workpiece is required, ground it directly with a separate cable.
- Do not touch electrode if you are in contact with the work, ground, or another electrode from a different machine.
- Use only well-maintained equipment. Repair or replace damaged parts at once. Maintain unit according to manual.
- Do not touch electrode holders connected to two welding machines at the same time since double open-circuit voltage will be present.
- Wear a safety harness if working above floor level.
- Keep all panels and covers securely in place.
- Clamp work cable with good metal-to-metal contact to workpiece or worktable as near the weld as practical.
- Insulate work clamp when not connected to workpiece to prevent contact with any metal object.
- Do not connect more than one electrode or work cable to any single weld output terminal. Disconnect cable for process not in use.
- Use GFCI protection when operating auxiliary equipment in damp or wet locations.



HOT PARTS can burn.

- Do not touch hot parts bare handed.
- Allow cooling period before working on equipment.
- To handle hot parts, use proper tools and/or wear heavy, insulated welding gloves and clothing to

prevent burns.



FLYING METAL OR DIRT can injure eyes.

- Welding, chipping, wire brushing, and grinding cause sparks and flying metal. As welds cool, they can throw off slag.

- Wear approved safety glasses with side shields even under your welding helmet.



FUMES AND GASES can be hazardous.

Welding produces fumes and gases. Breathing these fumes and gases can be hazardous to your health.

- Keep your head out of the fumes. Do not breathe the fumes.
- Ventilate the work area and/or use local forced ventilation at the arc to remove welding fumes and gases. The recommended way to determine adequate ventilation is to sample for the composition and quantity of fumes and gases to which personnel are exposed.
- If ventilation is poor, wear an approved air-supplied respirator.
- Read and understand the Safety Data Sheets (SDSs) and the manufacturer's instructions for adhesives, coatings, cleaners, consumables, coolants, degreasers, fluxes, and metals.
- Work in a confined space only if it is well ventilated, or while wearing an air-supplied respirator. Always have a trained watchperson nearby. Welding fumes and gases can displace air and lower the oxygen level causing injury or death. Be sure the breathing air is safe.
- Do not weld in locations near degreasing, cleaning, or spraying operations. The heat and rays of the arc can react with vapors to form highly toxic and irritating gases.
- Do not weld on coated metals, such as galvanized, lead, or cadmium plated steel, unless the coating is removed from the weld area, the area is well ventilated, and while wearing an air-supplied respirator. The coatings and any metals containing these elements can give off toxic fumes if welded.



BUILDUP OF GAS can injure or kill.

- Shut off compressed gas supply when not in use.
- Always ventilate confined spaces or use approved air-supplied respirator.



ARC RAYS can burn eyes and skin.

Arc rays from the welding process produce intense visible and invisible (ultraviolet and infrared) rays that can burn eyes and skin. Sparks fly off from the weld.


- Wear an approved welding helmet fitted with a proper shade of filter lenses to protect your face and eyes from arc rays and sparks when welding or watching (see ANSI Z49.1 and Z87.1 listed in Safety Standards).
- Wear approved safety glasses with side shields under your helmet.
- Use protective screens or barriers to protect others from flash, glare, and sparks; warn others not to watch the arc.
- Wear body protection made from leather or flame-resistant clothing (FRC). Body protection includes oil-free clothing such as leather gloves, heavy shirt, cuffless trousers, high shoes, and a cap.



WELDING can cause fire or explosion.

Welding on closed containers, such as tanks, drums, or pipes, can cause them to blow up. Sparks can fly off from the welding arc. The flying sparks, hot workpiece, and hot equipment can cause fires and burns. Accidental contact of electrode to metal objects can cause sparks, explosion, overheating, or fire. Check and be sure the area is safe before doing any welding.

- Remove all flammables within 35 ft (10.7 m) of the welding arc. If this is not possible, tightly cover them with approved covers.
- Do not weld where flying sparks can strike flammable material.
- Protect yourself and others from flying sparks and hot metal.
- Be alert that welding sparks and hot materials from welding can easily go through small cracks and openings to adjacent areas.
- Watch for fire, and keep a fire extinguisher nearby.
- Be aware that welding on a ceiling, floor, bulkhead, or partition can cause fire on the hidden side.
- Do not cut or weld on tire rims or wheels. Tires can explode if heated. Repaired rims and wheels can fail. See OSHA 29 CFR 1910.177 listed in Safety Standards.
- Do not weld on containers that have held combustibles, or on closed containers such as tanks, drums, or pipes unless they are properly prepared according to AWS F4.1 (see Safety Standards).
- Do not weld where the atmosphere can contain flammable dust, gas, or liquid vapors (such as gasoline).
- Connect work cable to the work as close to the welding area as practical to prevent welding current from traveling long, possibly unknown paths and causing electric shock, sparks, and fire hazards.
- Do not use welder to thaw frozen pipes.
- Remove stick electrode from holder or cut off welding wire at contact tip when not in use.
- Wear body protection made from leather or flame-resistant clothing (FRC). Body protection includes oil-free clothing such as leather gloves, heavy shirt, cuffless trousers, high shoes, and a cap.
- Remove any combustibles, such as a butane lighter or matches, from your person before doing any welding.
- After completion of work, inspect area to ensure it is free of sparks, glowing embers, and flames.
- Use only correct fuses or circuit breakers. Do not oversize or bypass them.
- Follow requirements in OSHA 1910.252 (a) (2) (iv) and NFPA 51B for hot work and have a fire watcher and extinguisher nearby.
- Read and understand the Safety Data Sheets (SDSs) and the manufacturer's instructions for adhesives, coatings, cleaners, consumables, coolants, degreasers, fluxes, and metals.



NOISE can damage hearing.

Noise from some processes or equipment can damage hearing.

- Wear approved ear protection if noise level is high.



ELECTRIC AND MAGNETIC FIELDS (EMF) can affect Implanted Medical Devices.

- Wearers of Pacemakers and other Implanted Medical Devices should keep away.

- Implanted Medical Device wearers should consult their doctor and the device manufacturer before going near arc welding, spot welding, gouging, plasma arc cutting, or induction heating operations.



CYLINDERS can explode if damaged.

Compressed gas cylinders contain gas under high pressure. If damaged, a cylinder can explode. Since gas cylinders are normally part of the welding process, be sure to treat them carefully.

- Protect compressed gas cylinders from excessive heat, mechanical shocks, physical damage, slag, open flames, sparks, and arcs.
- Install cylinders in an upright position by securing to a stationary support or cylinder rack to prevent falling or tipping.
- Keep cylinders away from any welding or other electrical circuits.
- Never drape a welding torch over a gas cylinder.
- Never allow a welding electrode to touch any cylinder.

- Never weld on a pressurized cylinder—explosion will result.
- Use only correct compressed gas cylinders, regulators, hoses, and fittings designed for the specific application; maintain them and associated parts in good condition.
- Turn face away from valve outlet when opening cylinder valve. Do not stand in front of or behind the regulator when opening the valve.
- Keep protective cap in place over valve except when cylinder is in use or connected for use.
- Use the proper equipment, correct procedures, and sufficient number of persons to lift, move, and transport cylinders.
- Read and follow instructions on compressed gas cylinders, associated equipment, and Compressed Gas Association (CGA) publication P-1 listed in Safety Standards.

1-3. Additional Hazards For Installation, Operation, And Maintenance




FIRE OR EXPLOSION hazard.

- Do not install or place unit on, over, or near combustible surfaces.
- Do not install unit near flammables.
- Do not overload building wiring—be sure power supply system is properly sized, rated, and protected to handle this unit.




FALLING EQUIPMENT can injure.

- Use lifting eye to lift unit only, NOT running gear, gas cylinders, or any other accessories.
- Use correct procedures and equipment of adequate capacity to lift and support unit.
- If using lift forks to move unit, be sure forks are long enough to extend beyond opposite side of unit.
- Keep equipment (cables and cords) away from moving vehicles when working from an aerial location.
- Follow the guidelines in the Applications Manual for the Revised NIOSH Lifting Equation (Publication No. 94-110) when manually lifting heavy parts or equipment.




OVERUSE can cause OVERHEATING.

- Allow cooling period; follow rated duty cycle.
- Reduce current or reduce duty cycle before starting to weld again.
- Do not block or filter airflow to unit.



FLYING SPARKS can injure.

- Wear a face shield to protect eyes and face.
- Shape tungsten electrode only on grinder with proper guards in a safe location wearing proper face, hand, and body protection.
- Sparks can cause fires—keep flammables away.



STATIC (ESD) can damage PC boards.

- Put on grounded wrist strap BEFORE handling boards or parts.
- Use proper static-proof bags and boxes to store, move, or ship PC boards.




MOVING PARTS can injure.

- Keep away from moving parts.
- Keep away from pinch points such as drive rolls.



WELDING WIRE can injure.

- Do not press gun trigger until instructed to do so.
- Do not point gun toward any part of the body, other people, or any metal when threading welding wire.




BATTERY EXPLOSION can injure.

- Do not use welder to charge batteries or jump start vehicles unless it has a battery charging feature designed for this purpose.



MOVING PARTS can injure.

- Keep away from moving parts such as fans.
- Keep all doors, panels, covers, and guards closed and securely in place.
- Have only qualified persons remove doors, panels, covers, or guards for maintenance and troubleshooting as necessary.
- Reinstall doors, panels, covers, or guards when maintenance is finished and before reconnecting input power.



READ INSTRUCTIONS.

- Read and follow all labels and the Owner's Manual carefully before installing, operating, or servicing unit. Read the safety information at the beginning of the manual and in each section.
- Use only genuine replacement parts from the manufacturer.
- Perform installation, maintenance, and service according to the Owner's Manuals, industry standards, and national, state, and local codes.



H.F. RADIATION can cause interference.

- High-frequency (H.F.) can interfere with radio navigation, safety services, computers, and communications equipment.
- Have only qualified persons familiar with electronic equipment perform this installation.
- The user is responsible for having a qualified electrician promptly correct any interference problem resulting from the installation.
- If notified by the FCC about interference, stop using the equipment at once.
- Have the installation regularly checked and maintained.
- Keep high-frequency source doors and panels tightly shut, keep spark gaps at correct setting, and use grounding and shielding to minimize the possibility of interference.



ARC WELDING can cause interference.

- Electromagnetic energy can interfere with sensitive electronic equipment such as microprocessors, computers, and computer-driven equipment such as robots.
- Be sure all equipment in the welding area is electromagnetically compatible.

- To reduce possible interference, keep weld cables as short as possible, close together, and down low, such as on the floor.
- Locate welding operation 100 meters from any sensitive electronic equipment.
- Be sure this welding machine is installed and grounded according to this manual.
- If interference still occurs, the user must take extra measures such as moving the welding machine, using shielded cables, using line filters, or shielding the work area.

1-4. California Proposition 65 Warnings

⚠ WARNING – This product can expose you to chemicals including lead, which are known to the state of California to cause cancer and birth defects or other reproductive harm.

For more information, go to www.P65Warnings.ca.gov.

1-5. Principal Safety Standards

Safety in Welding, Cutting, and Allied Processes, American Welding Society standard ANSI Standard Z49.1. Website: <http://www.aws.org>.

Safe Practice For Occupational And Educational Eye And Face Protection, ANSI Standard Z87.1, from American National Standards Institute. Website: www.ansi.org.

Safe Practices for the Preparation of Containers and Piping for Welding and Cutting, American Welding Society Standard AWS F4.1. Website: <http://www.aws.org>.

National Electrical Code, NFPA Standard 70 from National Fire Protection Association. Website: www.nfpa.org.

Safe Handling of Compressed Gases in Cylinders, CGA Pamphlet P-1 from Compressed Gas Association. Website: www.cganet.com.

Safety in Welding, Cutting, and Allied Processes, CSA Standard W117.2 from Canadian Standards Association. Website: www.csagroup.org.

Standard for Fire Prevention During Welding, Cutting, and Other Hot Work, NFPA Standard 51B from National Fire Protection Association. Website: www.nfpa.org.

OSHA, Occupational Safety and Health Standards for General Industry, Title 29, Code of Federal Regulations (CFR), Part 1910.177 Subpart N, Part 1910 Subpart Q, and Part 1926, Subpart J. Website: www.osha.gov.

OSHA Important Note Regarding the ACGIH TLV, Policy Statement on the Uses of TLVs and BEIs. Website: www.osha.gov.

Applications Manual for the Revised NIOSH Lifting Equation from the National Institute for Occupational Safety and Health (NIOSH). Website: www.cdc.gov/NIOSH.

SOM 2022-01

1-6. EMF Information

Electric current flowing through any conductor causes localized electric and magnetic fields (EMF). The current from arc welding (and allied processes including spot welding, gouging, plasma arc cutting, and induction heating operations) creates an EMF field around the welding circuit. EMF fields can interfere with some medical implants, e.g. pacemakers. Protective measures for persons wearing medical implants have to be taken. For example, restrict access for passers –by or conduct individual risk assessment for welders. All welders should use the following procedures in order to minimize exposure to EMF fields from the welding circuit:

1. Keep cables close together by twisting or taping them, or using a cable cover.
2. Do not place your body between welding cables. Arrange cables to one side and away from the operator.
3. Do not coil or drape cables around your body.

4. Keep head and trunk as far away from the equipment in the welding circuit as possible.
5. Connect work clamp to workpiece as close to the weld as possible.
6. Do not work next to, sit or lean on the welding power source.
7. Do not weld whilst carrying the welding power source or wire feeder.

About Implanted Medical Devices:

Implanted Medical Device wearers should consult their doctor and the device manufacturer before performing or going near arc welding, spot welding, gouging, plasma arc cutting, or induction heating operations. If cleared by your doctor, then following the above procedures is recommended.

SECTION 2 – CONSIGNES DE SÉCURITÉ - LIRE AVANT UTILISATION

⚠ Pour écarter les risques de blessure pour vous-même et pour autrui — lire, appliquer et ranger en lieu sûr ces consignes relatives aux précautions de sécurité et au mode opératoire.

2-1. Symboles utilisés

⚠ **DANGER!** – Indique une situation dangereuse qui si on l'évite pas peut donner la mort ou des blessures graves. Les dangers possibles sont montrés par les symboles joints ou sont expliqués dans le texte.

⚠ Indique une situation dangereuse qui si on l'évite pas peut donner la mort ou des blessures graves. Les dangers possibles sont montrés par les symboles joints ou sont expliqués dans le texte.

AVIS – Indique des déclarations pas en relation avec des blessures personnelles.

👉 Indique des instructions spécifiques.



Ce groupe de symboles veut dire Avertissement! Attention! DANGER DE CHOC ELECTRIQUE, PIECES EN MOUVEMENT, et PIECES CHAUDES. Reportez-vous aux symboles et aux directives ci-dessous afin de connaître les mesures à prendre pour éviter tout danger.

2-2. Dangers relatifs au soudage à l'arc



UNE DÉCHARGE ÉLECTRIQUE peut entraîner la mort.


Le contact d'organes électriques sous tension peut provoquer des accidents mortels ou des brûlures graves. Le circuit de l'électrode et de la pièce est sous tension lorsque le courant est délivré à la sortie. Le circuit d'alimentation et les circuits internes de la machine sont également sous tension lorsque l'alimentation est sur Marche. Dans le mode de soudage avec du fil, le fil, le dérouleur, le bloc de commande du rouleau et toutes les parties métalliques en contact avec le fil sont sous tension électrique. Un équipement installé ou mis à la terre de manière incorrecte ou impropre constitue un danger.

- Ne pas toucher aux pièces électriques sous tension.
- Porter des gants isolants et des vêtements de protection secs et sans trous.
- S'isoler de la pièce à couper et du sol en utilisant des housses ou des tapis assez grands afin d'éviter tout contact physique avec la pièce à couper ou le sol.
- Ne pas utiliser de sortie de soudage CA dans des zones humides ou confinées ou s'il y a un risque de chute.
- Se servir d'une source électrique à courant électrique UNIQUEMENT si le procédé de soudage le demande.
- Si l'utilisation d'une source électrique à courant électrique s'avère nécessaire, se servir de la fonction de télécommande si l'appareil en est équipé.
- D'autres consignes de sécurité sont nécessaires dans les conditions suivantes : risques électriques dans un environnement humide ou si l'on porte des vêtements mouillés ; sur des structures métalliques telles que sols, grilles ou échafaudages ; en position coincée comme assise, à genoux ou couchée ; ou s'il y a un risque élevé de contact inévitable ou accidentel avec la pièce à souder ou le sol. Dans ces conditions, utiliser les équipements suivants, dans l'ordre indiqué : 1) un poste à souder DC à tension constante (à fil), 2) un poste à souder DC manuel (électrode) ou 3) un poste à souder AC à tension à vide réduite. Dans la plupart des situations, l'utilisation d'un poste à souder DC à fil à tension constante est recommandée. En outre, ne pas travailler seul !
- Couper l'alimentation ou arrêter le moteur avant de procéder à l'installation, à la réparation ou à l'entretien de l'appareil. Déverrouiller l'alimentation selon la norme OSHA 29 CFR 1910.147 (voir normes de sécurité).
- Brancher correctement la mise à la terre et utiliser cet appareil conformément à son manuel d'utilisateur et aux codes nationaux, provinciaux et municipaux.
- Toujours vérifier la mise à la terre — vérifier et assurez-vous que le conducteur de mise à la terre du cordon d'alimentation est bien raccordé à la borne de mise à la terre dans le boîtier de connexion ou que la fiche du cordon est raccordée à une prise correctement mise à la terre.
- En effectuant les raccordements d'entrée, fixer d'abord le conducteur de mise à la terre approprié et contre-vérifier les connexions.
- Les câbles doivent être exempts d'humidité, d'huile et de graisse; protégez-les contre les étincelles et les pièces métalliques chaudes.
- Vérifier fréquemment le cordon d'alimentation et le conducteur de mise à la terre afin de s'assurer qu'il n'est pas altéré ou dénudé -, le remplacer immédiatement s'il l'est -. Un fil dénudé peut entraîner la mort.
- L'équipement doit être hors tension lorsqu'il n'est pas utilisé.
- Ne pas utiliser des câbles usés, endommagés, de grosseur insuffisante ou mal épissés.
- Ne pas enrouler les câbles autour du corps.
- Si la pièce soudée doit être mise à la terre, le faire directement avec un câble distinct.
- Ne pas toucher l'électrode quand on est en contact avec la pièce, la terre ou une électrode provenant d'une autre machine.
- Ne pas toucher des porte électrodes connectés à deux machines en même temps à cause de la présence d'une tension à vide doublée.
- N'utiliser qu'un matériel en bon état. Réparer ou remplacer sur-le-champ les pièces endommagées. Entretien l'appareil conformément à ce manuel.
- Porter un harnais de sécurité si l'on doit travailler au-dessus du sol.
- S'assurer que tous les panneaux et couvercles sont correctement en place.
- Fixer le câble de retour de façon à obtenir un bon contact métal-métal avec la pièce à souder ou la table de travail, le plus près possible de la soudure.
- Isoler la pince de masse quand pas mis à la pièce pour éviter le contact avec tout objet métallique.
- Ne pas raccorder plus d'une électrode ou plus d'un câble de masse à une même borne de sortie de soudage. Débrancher le câble pour le procédé non utilisé.
- Utiliser une protection différentielle lors de l'utilisation d'un équipement auxiliaire dans des endroits humides ou mouillés.



LES PIÈCES CHAUDES peuvent provoquer des brûlures.

- Ne pas toucher des parties chaudes à mains nues.
- Prévoir une période de refroidissement avant de travailler à l'équipement.
- Ne pas toucher aux pièces chaudes, utiliser les outils recommandés et porter des gants de soudage et des vêtements épais pour éviter les brûlures.



DES PIÈCES DE METAL ou DES SALETES peuvent provoquer des blessures dans les yeux.

- Le soudage, l'écaillage, le passage de la pièce à la brosse en fil de fer, et le meulage génèrent des étincelles et des particules métalliques volantes. Pendant la période de refroidissement des soudures, elles risquent de projeter du laitier.
- Porter des lunettes de sécurité avec écrans latéraux ou un écran facial.



LES FUMÉES ET LES GAZ peuvent être dangereux.

Le soudage génère des fumées et des gaz. Leur inhalation peut être dangereuse pour votre santé.

- Eloigner votre tête des fumées. Ne pas respirer les fumées.
- À l'intérieur, ventiler la zone et/ou utiliser une ventilation forcée au niveau de l'arc pour l'évacuation des fumées et des gaz de soudage. Pour déterminer la bonne ventilation, il est recommandé de procéder à un prélèvement pour la composition et la quantité de fumées et de gaz auxquelles est exposé le personnel.
- Si la ventilation est médiocre, porter un respirateur anti-vapeurs approuvé.
- Lire et comprendre les fiches de données de sécurité et les instructions du fabricant concernant les adhésifs, les revêtements, les nettoyants, les consommables, les produits de refroidissement, les dégraissants, les flux et les métaux.
- Travailler dans un espace fermé seulement s'il est bien ventilé ou en portant un respirateur à alimentation d'air. Demander toujours à un surveillant dûment formé de se tenir à proximité. Des fumées et des gaz de soudage peuvent déplacer l'air et abaisser le niveau d'oxygène provoquant des blessures ou des accidents mortels. S'assurer que l'air de respiration ne présente aucun danger.
- Ne pas souder dans des endroits situés à proximité d'opérations de dégraissage, de nettoyage ou de pulvérisation. La chaleur et les rayons de l'arc peuvent réagir en présence de vapeurs et former des gaz hautement toxiques et irritants.
- Ne pas souder des métaux munis d'un revêtement, tels que l'acier galvanisé, plaqué en plomb ou au cadmium à moins que le revêtement n'ait été enlevé dans la zone de soudure, que l'endroit soit bien ventilé, et en portant un respirateur à alimentation d'air. Les revêtements et tous les métaux renfermant ces éléments peuvent dégager des fumées toxiques en cas de soudage.



LES ACCUMULATIONS DE GAZ risquent de provoquer des blessures ou même la mort.

- Fermer l'alimentation du gaz comprimé en cas de non utilisation.
- Veiller toujours à bien aérer les espaces confinés ou se servir d'un respirateur d'adduction d'air homologué.



LES RAYONS DE L'ARC peuvent provoquer des brûlures dans les yeux et sur la peau.

Le rayonnement de l'arc du procédé de soudage génère des rayons visibles et invisibles intenses (ultraviolets et infrarouges) susceptibles de provoquer des brûlures dans les yeux et sur la peau. Des étincelles sont projetées pendant le soudage.

- Porter un casque de soudage approuvé muni de verres filtrants approprié pour protéger visage et yeux pendant le soudage (voir ANSI Z49.1 et Z87.1 énuméré dans les normes de sécurité).
- Porter des lunettes de sécurité avec écrans latéraux même sous votre casque.
- Avoir recours à des écrans protecteurs ou à des rideaux pour protéger les autres contre les rayonnements les éblouissements et les étincelles ; prévenir toute personne sur les lieux de ne pas regarder l'arc.
- Porter une protection corporelle en cuir ou des vêtements ignifuges (FRC). La protection du corps comporte des vêtements sans huile, comme des gants de cuir, une chemise solide, des pantalons sans revers, des chaussures hautes et une casquette.



LE SOUDAGE peut provoquer un incendie ou une explosion.

Le soudage effectué sur des conteneurs fermés tels que des réservoirs, tambours ou des conduites peut provoquer leur éclatement. Des étincelles peuvent être projetées de l'arc de soudure. La projection d'étincelles, des pièces chaudes et des équipements chauds peut provoquer des incendies et des brûlures. Le contact accidentel de l'électrode avec des objets métalliques peut provoquer des étincelles, une explosion, un surchauffement ou un incendie. Avant de commencer le soudage, vérifier et s'assurer que l'endroit ne présente pas de danger.

- Déplacer toutes les substances inflammables à une distance de 10,7 m de l'arc de soudage. En cas d'impossibilité les recouvrir soigneusement avec des protections homologués.
- Ne pas souder dans un endroit où des étincelles peuvent tomber sur des substances inflammables.
- Se protéger et d'autres personnes de la projection d'étincelles et de métal chaud.
- Des étincelles et des matériaux chauds du soudage peuvent facilement passer dans d'autres zones en traversant de petites fissures et des ouvertures.
- Surveiller tout déclenchement d'incendie et tenir un extincteur à proximité.
- Le soudage effectué sur un plafond, plancher, paroi ou séparation peut déclencher un incendie de l'autre côté.
- Ne pas couper ou souder des jantes ou des roues. Les pneus peuvent exploser s'ils sont chauffés. Les jantes et les roues réparées peuvent défaillir. Voir OSHA 29 CFR 1910.177 énuméré dans les normes de sécurité.
- Ne pas effectuer le soudage sur des conteneurs fermés tels que des réservoirs, tambours, ou conduites, à moins qu'ils n'aient été préparés correctement conformément à AWS F4.1 (voir les Normes de Sécurité).
- Ne pas souder là où l'air ambiant pourrait contenir des poussières, gaz ou émanations inflammables (vapeur d'essence, par exemple).
- Brancher le câble de masse sur la pièce le plus près possible de la zone de soudage pour éviter le transport du courant sur une longue distance par des chemins inconnus éventuels en provoquant des risques d'électrocution, d'étincelles et d'incendie.
- Ne pas utiliser le poste de soudage pour dégelier des conduites gelées.
- En cas de non utilisation, enlever la baguette d'électrode du porte-électrode ou couper le fil à la pointe de contact.

- Porter une protection corporelle en cuir ou des vêtements ignifuges (FRC). La protection du corps comporte des vêtements sans huile, comme des gants de cuir, une chemise solide, des pantalons sans revers, des chaussures hautes et une casquette.
- Avant de souder, retirer toute substance combustible de vos poches telles qu'un allumeur au butane ou des allumettes.
- Une fois le travail achevé, assurez-vous qu'il ne reste aucune trace d'étincelles incandescentes ni de flammes.
- Utiliser exclusivement des fusibles ou coupe-circuits appropriés. Ne pas augmenter leur puissance; ne pas les ponter.
- Suivre les recommandations dans OSHA 1910.252 (a) (2) (iv) et NFPA 51B pour les travaux à chaud et avoir de la surveillance et un extincteur à proximité.
- Lire et comprendre les fiches de données de sécurité et les instructions du fabricant concernant les adhésifs, les revêtements, les nettoyants, les consommables, les produits de refroidissement, les dégraisseurs, les flux et les métaux.



Le BRUIT peut endommager l'ouïe.


Le bruit des processus et des équipements peut affecter l'ouïe.

- Porter des protections approuvées pour les oreilles si le niveau sonore est trop élevé.



Les CHAMPS ÉLECTROMAGNÉTIQUES (CEM) peuvent affecter les implants médicaux.

- Les porteurs de stimulateurs cardiaques et autres implants médicaux doivent rester à distance.
- Les porteurs d'implants médicaux doivent consulter leur médecin et le fabricant du dispositif avant de s'approcher de la zone où se déroule le soudage à l'arc, du soudage par points, du gougeage, de la découpe plasma ou une opération de chauffage par induction.



Si des BOUTEILLES sont endommagées, elles pourront exploser.

Des bouteilles de gaz comprimé protecteur contiennent du gaz sous haute pression. Si une bouteille est endommagée, elle peut exploser. Du fait que les bouteilles de gaz font normalement partie du procédé de soudage, les manipuler avec précaution.


- Protéger les bouteilles de gaz comprimé d'une chaleur excessive, des chocs mécaniques, des dommages physiques, du laitier, des flammes ouvertes, des étincelles et des arcs.
- Placer les bouteilles debout en les fixant dans un support stationnaire ou dans un porte-bouteilles pour les empêcher de tomber ou de se renverser.
- Tenir les bouteilles éloignées des circuits de soudage ou autres circuits électriques.
- Ne jamais placer une torche de soudage sur une bouteille à gaz.
- Une électrode de soudage ne doit jamais entrer en contact avec une bouteille.
- Ne jamais souder une bouteille pressurisée - risque d'explosion.
- Utiliser seulement des bouteilles de gaz comprimé, régulateurs, tuyaux et raccords convenables pour cette application spécifique; les maintenir ainsi que les éléments associés en bon état.
- Tourner le dos à la sortie de vanne lors de l'ouverture de la vanne de la bouteille. Ne pas se tenir devant ou derrière le régulateur lors de l'ouverture de la vanne.
- Maintenir le chapeau de protection sur la soupape, sauf en cas d'utilisation ou de branchement de la bouteille.
- Utilisez les équipements corrects, les bonnes procédures et suffisamment de personnes pour soulever, déplacer et transporter les bouteilles.
- Lire et suivre les instructions sur les bouteilles de gaz comprimé, l'équipement connexe et le dépliant P-1 de la CGA (Compressed Gas Association) mentionné dans les principales normes de sécurité.

2-3. Symboles de dangers supplémentaires en relation avec l'installation, le fonctionnement et la maintenance



Risque D'INCENDIE OU D'EXPLOSION.

- Ne pas placer l'appareil sur, au-dessus ou à proximité de surfaces inflammables.
- Ne pas installer l'appareil à proximité de produits inflammables
- Ne pas surcharger l'installation électrique – s'assurer que l'alimentation est correctement dimensionnée et protégée avant de mettre l'appareil en service.




L'EMPLOI EXCESSIF peut SURCHAUFFER L'ÉQUIPEMENT.

- Laisser l'équipement refroidir ; respecter le facteur de marche nominal.
- Réduire le courant ou le cycle opératoire avant de recommencer le soudage.
- Ne pas obstruer les passages d'air du poste.




LA CHUTE DE L'ÉQUIPEMENT peut provoquer des blessures.

- Utiliser l'anneau de levage uniquement pour soulever l'appareil, NON PAS les organes de roulement, les bouteilles de gaz ou tout autre accessoire.
- Utilisez les procédures correctes et des équipements d'une capacité appropriée pour soulever et supporter l'appareil.
- En utilisant des fourches de levage pour déplacer l'unité, s'assurer que les fourches sont suffisamment longues pour dépasser du côté opposé de l'appareil.
- Tenir l'équipement (câbles et cordons) à distance des véhicules mobiles lors de toute opération en hauteur.
- Suivre les consignes du Manuel des applications pour l'équation de levage NIOSH révisée (Publication N°94-110) lors du levage manuel de pièces ou équipements lourds.



LES ÉTINCELLES PROJÉTÉES peuvent provoquer des blessures.

- Porter un écran facial pour protéger le visage et les yeux.
- Affûter l'électrode au tungstène uniquement à la meuleuse dotée de protecteurs. Cette manœuvre est à exécuter dans un endroit sûr lorsque l'on porte l'équipement homologué de protection du visage, des mains et du corps.
- Les étincelles risquent de causer un incendie - éloigner toute substance inflammable.



LES CHARGES ÉLECTROSTATIQUES peuvent endommager les circuits imprimés.

- Établir la connexion avec la barrette de terre AVANT de manipuler des cartes ou des pièces.

- Utiliser des pochettes et des boîtes antistatiques pour stocker, déplacer ou expédier des cartes de circuits imprimés.



Les PIÈCES MOBILES peuvent causer des blessures.

- Ne pas s'approcher des organes mobiles.
- Ne pas s'approcher des points de coincement tels que des rouleaux de commande.



LES FILS DE SOUDAGE peuvent provoquer des blessures.

- Ne pas appuyer sur la gachette avant d'en avoir reçu l'instruction.
- Ne pas diriger le pistolet vers soi, d'autres personnes ou toute pièce mécanique en engageant le fil de soudage.




L'EXPLOSION DE LA BATTERIE peut provoquer des blessures.

- Ne pas utiliser l'appareil de soudage pour charger des batteries ou faire démarrer des véhicules à l'aide de câbles de démarrage, sauf si l'appareil dispose d'une fonctionnalité de charge de batterie destinée à cet usage.



Les PIÈCES MOBILES peuvent causer des blessures.


- S'abstenir de toucher des organes mobiles tels que des ventilateurs.
- Maintenir fermés et verrouillés les portes, panneaux, recouvrements et dispositifs de protection.
- Lorsque cela est nécessaire pour des travaux d'entretien et de dépannage, faire retirer les portes, panneaux, recouvrements ou dispositifs de protection uniquement par du personnel qualifié.
- Remettre les portes, panneaux, recouvrements ou dispositifs de protection quand l'entretien est terminé et avant de rebrancher l'alimentation électrique.



LIRE LES INSTRUCTIONS.


- Lire et appliquer les instructions sur les étiquettes et le Mode d'emploi avant l'installation, l'utilisation ou l'entretien de l'appareil. Lire les informations de sécurité au début du manuel et dans chaque section.
- N'utiliser que des pièces de remplacement provenant du fabricant.

- Effectuer l'installation, l'entretien et toute intervention selon les manuels d'utilisateurs, les normes nationales, provinciales et de l'industrie, ainsi que les codes municipaux.



LE RAYONNEMENT HAUTE FRÉQUENCE (H.F.) risque de provoquer des interférences.

- Le rayonnement haute fréquence (H.F.) peut provoquer des interférences avec les équipements de radio-navigation et de communication, les services de sécurité et les ordinateurs.
- Demander seulement à des personnes qualifiées familiarisées avec des équipements électroniques de faire fonctionner l'installation.
- L'utilisateur est tenu de faire corriger rapidement par un électricien qualifié les interférences résultant de l'installation.
- Si le FCC signale des interférences, arrêter immédiatement l'appareil.
- Effectuer régulièrement le contrôle et l'entretien de l'installation.
- Maintenir soigneusement fermés les portes et les panneaux des sources de haute fréquence, maintenir les éclateurs à une distance correcte et utiliser une terre et un blindage pour réduire les interférences éventuelles.



LE SOUDAGE À L'ARC risque de provoquer des interférences.

- L'énergie électromagnétique risque de provoquer des interférences pour l'équipement électronique sensible tel que les ordinateurs et l'équipement commandé par ordinateur tel que les robots.
- Veiller à ce que tout l'équipement de la zone de soudage soit compatible électromagnétiquement.
- Pour réduire la possibilité d'interférence, maintenir les câbles de soudage aussi courts que possible, les grouper, et les poser aussi bas que possible (ex. par terre).
- Veiller à souder à une distance de 100 mètres de tout équipement électronique sensible.
- Veiller à ce que ce poste de soudage soit posé et mis à la terre conformément à ce mode d'emploi.
- En cas d'interférences après avoir pris les mesures précédentes, il incombe à l'utilisateur de prendre des mesures supplémentaires telles que le déplacement du poste, l'utilisation de câbles blindés, l'utilisation de filtres de ligne ou la pose de protecteurs dans la zone de travail.

2-4. Proposition californienne 65 Avertissements

⚠ AVERTISSEMENT – Ce produit peut vous exposer à des produits chimiques tels que le plomb, reconnus par l'État de Californie comme cancérigènes et sources de malformations ou d'autres troubles de la reproduction.

Pour plus d'informations, consulter www.P65Warnings.ca.gov.

2-5. Principales normes de sécurité

Safety in Welding, Cutting, and Allied Processes, American Welding Society standard ANSI Standard Z49.1. Website: <http://www.aws.org>.

Safe Practice For Occupational And Educational Eye And Face Protection, ANSI Standard Z87.1, from American National Standards Institute. Website: www.ansi.org.

Safe Practices for the Preparation of Containers and Piping for Welding and Cutting, American Welding Society Standard AWS F4.1. Website: <http://www.aws.org>.

National Electrical Code, NFPA Standard 70 from National Fire Protection Association. Website: www.nfpa.org.

Safe Handling of Compressed Gases in Cylinders, CGA Pamphlet P-1 from Compressed Gas Association. Website: www.cganet.com.

Safety in Welding, Cutting, and Allied Processes, CSA Standard W117.2 from Canadian Standards Association. Website: www.csagroup.org.

Standard for Fire Prevention During Welding, Cutting, and Other Hot Work, NFPA Standard 51B from National Fire Protection Association. Website: www.nfpa.org.

OSHA, Occupational Safety and Health Standards for General Industry, Title 29, Code of Federal Regulations (CFR), Part 1910.177 Subpart N, Part 1910 Subpart Q, and Part 1926, Subpart J. Website: www.osha.gov.

OSHA *Important Note Regarding the ACGIH TLV, Policy Statement on the Uses of TLVs and BEIs*. Website: www.osha.gov.

Applications Manual for the Revised NIOSH Lifting Equation from the National Institute for Occupational Safety and Health (NIOSH). Website: www.cdc.gov/NIOSH.

SOM_fre 2022-01

2-6. Informations relatives aux CEM

Le courant électrique qui traverse tout conducteur génère des champs électromagnétiques (CEM) à certains endroits. Le courant issu d'un soudage à l'arc (et de procédés connexes, y compris le soudage par points, le gougeage, le découpage plasma et les opérations de chauffage par induction) crée un champ électromagnétique (CEM) autour du circuit de soudage. Les champs électromagnétiques produits peuvent causer interférence à certains implants médicaux, p. ex. les stimulateurs cardiaques. Des mesures de protection pour les porteurs d'implants médicaux doivent être prises: par exemple, des restrictions d'accès pour les passants ou une évaluation individuelle des risques pour les soudeurs. Tous les soudeurs doivent appliquer les procédures suivantes pour minimiser l'exposition aux CEM provenant du circuit de soudage:

1. Rassembler les câbles en les torsadant ou en les attachant avec du ruban adhésif ou avec une housse.
2. Ne pas se tenir au milieu des câbles de soudage. Disposer les câbles d'un côté et à distance de l'opérateur.


3. Ne pas courber et ne pas entourer les câbles autour de votre corps.
4. Maintenir la tête et le torse aussi loin que possible du matériel du circuit de soudage.
5. Connecter la pince sur la pièce aussi près que possible de la soudure.
6. Ne pas travailler à proximité d'une source de soudage, ni s'asseoir ou se pencher dessus.
7. Ne pas souder tout en portant la source de soudage ou le dévidoir.










En ce qui concerne les implants médicaux :










Les porteurs d'implants doivent d'abord consulter leur médecin avant de s'approcher des opérations de soudage à l'arc, de soudage par points, de gougeage, du coupage plasma ou de chauffage par induction. Si le médecin approuve, il est recommandé de suivre les procédures précédentes.


SECTION 3 – DEFINITIONS

3-1. Additional Safety Symbol Definitions


 Some symbols are found only on CE products.

	<p>Warning! Watch Out! There are possible hazards as shown by the symbols.</p>
	<p>Wear dry insulating gloves. Do not touch electrode with bare hand. Do not wear wet or damaged gloves.</p>
	<p>Protect yourself from electric shock by insulating yourself from work and ground.</p>
	<p>Disconnect input plug or power before working on machine.</p>
	<p>Keep your head out of the fumes.</p>
	<p>Use forced ventilation or local exhaust to remove the fumes.</p>
	<p>Use ventilating fan to remove fumes.</p>
	<p>Keep flammables away from welding. Do not weld near flammables.</p>
	<p>Welding sparks can cause fires. Have a fire extinguisher nearby, and have a watchperson ready to use it.</p>

	<p>Do not weld on drums or any closed containers.</p>
	<p>Do not remove or paint over (cover) the label.</p>
	<p>Disconnect input plug or power before working on machine.</p>
	<p>Consult rating label for input power requirements.</p>
	<p>Read Owner's Manual and inside labels for connection points and procedures.</p>
	<p>Do not discard product (where applicable) with general waste. Reuse or recycle Waste Electrical and Electronic Equipment (WEEE) by disposing at a designated collection facility. Contact your local recycling office or your local distributor for further information.</p>
	<p>Environmental Protection Use Period (China)</p>
	<p>Wear hat and safety glasses. Use ear protection and button shirt collar. Use welding helmet with correct shade of filter. Wear complete body protection made from leather or flame-resistant clothing (FRC). Body protection includes oil-free clothing such as leather gloves, heavy shirt, cuffless trousers, high shoes, and a cap.</p>
	<p>Become trained and read the instructions before working on the machine or welding.</p>



Move jumper links as shown on inside label to match input voltage at job site. Include extra length in grounding conductor and connect grounding conductor first. Connect line input conductors as shown on inside label. Double-check all connections, jumper link positions, and input voltage before applying power.



Close door before turning on unit.

3-2. Miscellaneous Symbol Definitions

A	Amperage
V	Voltage
Hz	Hertz
	Output
	Input
	Circuit Breaker
	Amperage/Voltage Control-Panel
	Remote
U₀	Rated No Load Voltage
U₁	Rated Supply Voltage
U₂	Conventional Load Voltage
S₁	Product of Voltage and Current (KVA)
I	On
O	Off
I₁	Rated Supply Current

I₂	Rated Welding Current
X	Duty Cycle
IP	Internal Protection Rating
	Suitable For Welding In An Environment With Increased Risk Of Electrical Shock
	Line Connection
	Three-Phase Transformer Rectifier
%	Percent
	Direct Current (DC)
3~	Three Phase
	Protective Earth (Ground)
	Negative Weld Output Terminal
	Positive Low Inductance Weld Output Terminal
	Positive High Inductance Weld Output Terminal
	Temperature
	Gas Metal Arc Welding (GMAW)

	Shielded Metal Arc Welding (SMAW)
	Gas Tungsten Arc Welding (GTAW)
	Submerged Arc Welding (SAW)
	Arc Force (DIG)
1~	Single Phase
	Start
	Stop
	Wire Feed Reverse
	Wire Feed Forward
	Crater Time
	Program
	Hopper
	Gas Postflow
	Gas Preflow
	Start Time

SECTION 4 – SPECIFICATIONS

4-1. Serial Number And Rating Label Location

The serial number and rating information is located on the left side of the unit. Use rating label to determine input power requirements and/or rated output. For future reference, write serial number in space provided on back cover of this manual.

4-2. Software Licensing Agreement

The End User License Agreement and any third-party notices and terms and conditions pertaining to third-party software can be found at <https://www.millerwelds.com/eula> and are incorporated by reference herein.

4-3. Information About Default Weld Parameters And Settings

NOTICE – Each welding application is unique. Although certain Miller Electric products are designed to determine and default to certain typical welding parameters and settings based upon specific and relatively limited application variables input by the end user, such default settings are for reference purposes only; and final weld results can be affected by other variables and application-specific circumstances. The appropriateness of all parameters and settings should be evaluated and modified by the end user as necessary based upon application-specific requirements. The end user is solely responsible for selection and coordination of appropriate equipment, adoption or adjustment of default weld parameters and settings, and ultimate quality and durability of all resultant welds. Miller Electric expressly disclaims any and all implied warranties including any implied warranty of fitness for a particular purpose.

4-4. Specifications

☞ Do not use information in unit specifications table to determine electrical service requirements. See Sections 5-4 thru 5-8 for information on connecting input power.

☞ This equipment will deliver rated output at an ambient air temperature up to 104°F (40°C).

Model	Rated Welding Output**	Amperage/Voltage Range DC	Max OCV-DC	Amperes Input at Rated Load Output, 60 Hz, Three-Phase			Amperes Input at Rated Load Output, 50 Hz, Three-Phase			KVA	KW
				230 V	460 V	575 V	380 V	400 V	440 V		
DC 650 Digital	650 A @ 44 Volts DC, 100% Duty Cycle	50 - 815 A In CC Mode	75 Vpk	126 3.8*	63 1.9*	50.4 1.4*				50 1.52*	34.8 0.76*
DC 800 Digital	815 A @ 44 Volts DC, 60% Duty Cycle	20 - 44 V In SubArc Mode					95 1.9*	90 1.8*	83 1.6*		
DC 1000 Digital	1000 A @ 44 Volts DC, 100% Duty Cycle	100 - 1250 A In CC Mode	68 Vpk	180 5.8*	90 2.9*	72 2.4*				73 3.2*	53 0.5*
DC 1250 Digital	1250 A @ 44 Volts DC, 60% Duty Cycle	20 - 44 V In SubArc Mode					135 5.2*	128 5.0*	117 4.5*		

4-5. SubArc System Compatibility

The following accessory models will function with the SubArc DC 650/800 and 1000/1250 Digital power sources. The interface will automatically detect the power source and wire drive type connected.

Interfaces:

300936 - SubArc Interface Digital

300937 - SubArc Interface Analog

Wire Drives:

300938 - SubArc Wire Drive 400 Digital Low Voltage

300938001 - SubArc Wire Drive 400 Digital Low Voltage For Tractors

300939 - SubArc Strip Drive 100 Digital Low Voltage

300940 - SubArc Strip Drive 100 Digital Low Voltage w/Mounting Bracket

300941 - SubArc Wire Drive 780 Digital Low Voltage

Flux Hopper:

300942 - SubArc Flux Hopper Digital Low Voltage

4-6. Static Characteristics


The static (output) characteristics of the welding power source can be described as *drooping* during the SAW process. Static characteristics are also affected by control settings (including software), electrode, shielding gas, weldment material, and other factors. Contact the factory for specific information on the static characteristics of the welding power source.

4-7. Environmental Specifications

A. IP Rating For All Equipment Covered In This Manual

IP Rating
IP23 This equipment is designed for outdoor use.

B. Information On Electromagnetic Compatibility (EMC) For DC 1000/1250 Amp Power Source Models

 **This Class A equipment is not intended for use in residential locations where the electrical power is provided by the public low-voltage supply system. There can be potential difficulties in ensuring electromagnetic compatibility in those locations, due to conducted as well as radiated disturbances.**


IEC/TS 61000-3-4 can be used to guide parties concerned by the installation of arc welding equipment with an input current greater than 75A in a low-voltage network.

C. Temperature Specifications

Operating Temperature Range*	Storage/Transportation Temperature Range
14 to 104°F (-10 to 40°C)	-4 to 131°F (-20 to 55°C)


*Output is derated at temperatures above 104°F (40°C).

D. EU Ecodesign Information

	<p>Do not discard product (where applicable) with general waste. Reuse or recycle Waste Electrical and Electronic Equipment (WEEE) by disposing at a designated collection facility. Contact your local recycling office or your local distributor for further information.</p>
---	---

Critical raw materials possibly present in indicative amounts higher than 1 gram at component level	
Component	Critical Raw Material
Printed circuit boards	Baryte, Bismuth, Cobalt, Gallium, Germanium, Hafnium, Indium, Heavy Rare Earth, Light Rare Earth, Niobium, Platinum Group Metals, Scandium, Silicon Metal, Tantalum, Vanadium
Plastic components	Antimony, Baryte
Electrical and electronic components	Antimony, Beryllium, Magnesium
Metal components	Beryllium, Cobalt, Magnesium, Tungsten, Vanadium
Cables and cable assemblies	Borate, Antimony, Baryte, Beryllium, Magnesium
Display panels	Gallium, Indium, Heavy Rare Earth, Light Rare Earth, Niobium, Platinum Group Metals, Scandium
Batteries	Fluorspar, Heavy Rare Earth, Light Rare Earth, Magnesium

E. China EEP Hazardous Substance Information


中国电器电子产品中有害物质的名称及含量 China EEP Hazardous Substance Information						
部件名称 Component Name (如果适用) (if applicable)	有害物质 Hazardous Substance					
	铅 Pb	汞 Hg	镉 Cd	六价铬 Cr6	多溴联苯 PBB	多溴二苯醚 PBDE
黄铜和铜部件 Brass and Copper Parts	X	O	O	O	O	O
耦合装置 Coupling Devices	X	O	O	O	O	O
开关装置 Switching Devices	O	O	X	O	O	O
线缆和线缆配件 Cable and Cable Accessories	X	O	O	O	O	O
电池 Batteries	X	O	O	O	O	O
本表格依据中国SJ/T 11364的规定编制。 This table is prepared in accordance with China SJ/T 11364.						
O: 表示该有害物质在该部件所有均质材料中的含量均在中国GB/T26572规定的限量要求以下。 Indicates that the concentration of the Hazardous Substance in all homogeneous materials of the part is below the relevant threshold of China GB/T 26572.						
X: 表示该有害物质至少在该部件的某一均质材料中的含量超出中国GB/T26572规定的限量要求。 Indicates that the concentration of the Hazardous Substance in at least one homogeneous material of the part is above the relevant threshold of China GB/T 26572.						
器电子产品的环保使用期限依据中国SJ/Z11388的规定确定。 The EFUP value of this EEP is defined in accordance with China SJ/Z 11388.						

4-8. Duty Cycle And Overheating

A. Duty Cycle And Overheating For DC 650/800 Amp Models



100% Duty Cycle




Continuous Welding


Duty cycle is the percentage of 10 minutes that unit can weld at rated load without overheating.

If unit overheats, thermostat(s) open, output stops, and cooling fan runs. Wait fifteen minutes for unit to cool. Reduce amperage or duty cycle before welding.

NOTICE – Exceeding duty cycle can damage unit and void warranty.




Overheating



B. Duty Cycle And Over Heating For DC 1000/1250 Amp Models



100% Duty Cycle




Continuous Welding

Duty cycle is the percentage of 10 minutes that unit can weld at rated load without overheating.


If unit overheats, thermostat(s) open, output stops, and cooling fan runs. Wait fifteen minutes for unit to cool. Reduce amperage or duty cycle before welding.

NOTICE – Exceeding duty cycle can damage unit and void warranty.




191157-B

Overheating



SECTION 5 – INSTALLATION


5-1. Dimensions And Weights





800453-B / 801530

Dimensions	
A	30 in. (762 mm) Including lift eye
B	23 in. (584 mm)
C	38 in. (965 mm) Including strain relief
D	33-3/4 in. (857 mm)
E	1-1/4 in. (32 mm)
F	20 in. (508 mm)
G	1-1/8 in. (29 mm)
H	7/16 in. (11 mm) Dia.
Weight	
650/800 Amp Models: 545 lb (247 kg)	
1000 Amp Models: 644 lb (292 kg)	
1250 Amp Models: 650 lb (295 kg)	


5-2. Selecting A Location



Movement



Location And Airflow



⚠ Do not move or operate unit where it could tip.

⚠ Special installation may be required where gasoline or volatile liquids are present - see NEC Article 511 or CEC Section 20.

1 Lifting Eye

2 Lifting Forks


Use lifting eye or lifting forks to move unit.

If using lifting forks, extend forks beyond opposite side of unit.

3 Line Disconnect Device

Locate unit near correct input power supply.

5-3. Typical Equipment Location



1 Welding Power Source

2 Side Beam

3 Interface

4 Spool Support

5 Wire Drive Assembly

6 Torch

Ref. 131138-A

5-4. Electrical Service Guide

A. Electrical Service Guide For DC 650/800 Digital Models

⚠ Failure to follow these electrical service guide recommendations could create an electric shock or fire hazard. These recommendations are for an individual branch circuit sized for the rated output and duty cycle of one welding power source. In individual branch circuit installations, the National Electrical Code (NEC) allows the receptacle or conductor rating to be less than the rating of the circuit protection device. All components of the circuit must be physically compatible. See NEC articles 210.21, 630.11, and 630.12.

⚠ CE-marked equipment shall only be used on a supply network that is a three-phase, four-wire system with an earthed neutral.

	60 Hz Models (DC 650 Digital)			50 Hz Models (DC 800 Digital)		
	250	460	575	380	400	440
Rated Supply Voltage (V)	250	460	575	380	400	440
Rated Maximum Supply Current I_{1max} (A)	155.0	78.0	62.0	95.0	90.0	83.0
Rated Effective Supply Current I_{1eff} (A)	120.6	60.7	48.2	73.8	69.7	64.3
Maximum Recommended Standard Fuse Rating In Amperes¹						
Time Delay Fuses²	175	90	70	110	110	100
Normal Operating Fuses³	225	110	90	125	125	110
Maximum Recommended Supply Conductor Length In Feet (Meters)⁴	167 (51)	259 (79)	267 (81)	287 (88)	319 (97)	257 (78)
Raceway Installation						
Minimum Supply Conductor Size In AWG (mm²)⁵	1 (50)	6 (16)	8 (10)	4 (25)	4 (25)	6 (16)
Minimum Grounding Conductor Size In AWG (mm²)⁵	4 (25)	6 (16)	8 (10)	6 (16)	6 (16)	6 (16)
Flexible Cord Installation						
Minimum Supply Conductor Size In AWG (mm²)⁶	*	2 (35)	4 (25)	2 (35)	2 (35)	2 (35)
Recommended Strain Relief⁷	Customer Supplied	Customer Supplied	Customer Supplied	Customer Supplied	Customer Supplied	Customer Supplied

* Connect per raceway installation

Reference: 2020 National Electrical Code (NEC) (including article 630)

1 If a circuit breaker is used in place of a fuse, choose a circuit breaker with time-current curves comparable to the recommended fuse.

2 "Time-Delay" fuses are UL class "RK5" . See UL 248.

3 "Normal Operating" (general purpose - no intentional delay) fuses are UL class "K5" (up to and including 60 amps), and UL class "H" (65 amps and above).

4 Maximum total length of copper input conductors in entire installation, raceway and/or flexible cord.

5 Raceway conductor data in this section specifies conductor size (excluding flexible cord or cable) between the panelboard and the equipment per NEC Table 310.15(B)(16) and is based on allowable ampacities of insulated copper conductors having a temperature rating of 75°C (167°F) with not more than three single current-carrying conductors in a raceway.

6 Flexible cord conductor size is based on NEC Table 400.5(A)(1) for SOOW 600V 90°C (194°F) jacketed cable in a 30°C (86°F) ambient temperature. See NEC Table 310.15(B)(2)(a) for ambient temperature correction factors. Flexible cord used for connection to the power supply system shall comply with the requirements of CSA C22.2 No. 49.

7 If necessary, have a qualified person enlarge access hole in machine panel to accommodate strain relief.

B. Electrical Service Guide For DC 1000/1250 Digital Models

⚠ Failure to follow these electrical service guide recommendations could create an electric shock or fire hazard. These recommendations are for an individual branch circuit sized for the rated output and duty cycle of one welding power source. In individual branch circuit installations, the National Electrical Code (NEC) allows the receptacle or conductor rating to be less than the rating of the circuit protection device. All components of the circuit must be physically compatible. See NEC articles 210.21, 630.11, and 630.12.

⚠ CE-marked equipment shall only be used on a supply network that is a three-phase, four-wire system with an earthed neutral.

	60 Hz Models (DC 1000 Digital)			50 Hz Models (DC 1250 Digital)		
Rated Supply Voltage (V)	230	460	575	380	400	440
Rated Maximum Supply Current I_{1max} (A)	223.0	112.0	89.0	135.0	128.0	117.0
Rated Effective Supply Current I_{1eff} (A)	173.5	86.7	64.4	105.1	99.6	91.1
Maximum Recommended Standard Fuse Rating In Amperes						
Time Delay Fuses ²	250	125	110	150	150	125
Normal Operating Fuses ³	300	150	125	200	175	175
Maximum Recommended Supply Conductor Length In Feet (Meters)⁴	159 (49)	303 (92)	261 (80)	252 (77)	231 (70)	278 (85)
Raceway Installation						
Minimum Supply Conductor Size In AWG (mm²) ⁵	2/0 (70)	3 (35)	6 (16)	2 (35)	3 (35)	3 (35)
Minimum Grounding Conductor Size In AWG (mm²) ⁵	4 (25)	6 (35)	6 (16)	6 (16)	6 (16)	6 (16)
Flexible Cord Installation						
Minimum Supply Conductor Size In AWG (mm²) ⁶	*	*	2 (35)	*	*	*
Recommended Strain Relief ⁷	Customer Supplied	Customer Supplied	Customer Supplied	Customer Supplied	Customer Supplied	Customer Supplied

* Connect per raceway installation

Reference: 2020 National Electrical Code (NEC) (including article 630)

1 If a circuit breaker is used in place of a fuse, choose a circuit breaker with time-current curves comparable to the recommended fuse.

2 "Time-Delay" fuses are UL class "RK5" . See UL 248.

3 "Normal Operating" (general purpose - no intentional delay) fuses are UL class "K5" (up to and including 60 amps), and UL class "H" (65 amps and above).

4 Maximum total length of copper input conductors in entire installation, raceway and/or flexible cord.

5 Raceway conductor data in this section specifies conductor size (excluding flexible cord or cable) between the panelboard and the equipment per NEC Table 310.15(B)(16) and is based on allowable ampacities of insulated copper conductors having a temperature rating of 75°C (167°F) with not more than three single current-carrying conductors in a raceway.





6 Flexible cord conductor size is based on NEC Table 400.5(A)(1) for SOOW 600V 90°C (194°F) jacketed cable in a 30°C (86°F) ambient temperature. See NEC Table 310.15(B)(2)(a) for ambient temperature correction factors. Flexible cord used for connection to the power supply system shall comply with the requirements of CSA C22.2 No. 49.

7 If necessary, have a qualified person enlarge access hole in machine panel to accommodate strain relief.


5-5. Placing Jumper Links



DC 650/800 Digital Model Shown



Ref. 265207-A

 3/8 in.

 3/8 in.

⚠ Disconnect and lockout/tagout input power before installing or moving jumper links. Follow established procedures regarding the installation and removal of lockout/tagout devices.


Check input voltage available at site.

- 1 Jumper Link Label For DC 800 Digital and DC 1250 Digital Machines
- 2 Jumper Link Label For DC 650 Digital and DC 1000 Digital Machines
- 3 Jumper Links
- 4 Do not over tighten jumper link nuts.

Move jumper links to match input voltage.

Close and secure access door, or go on to Section 5-6.

5-6. Connecting 3-Phase Input Power For DC 650/800 Models



Ref. input3 2015--01--Ref. 803766-C / 800103-D / Ref. 801116-A



5-7. Connecting 3-Phase Input Power For DC 650/800 Models (Continued)



⚠ Installation must meet all National and Local Codes – have only qualified persons make this installation.

⚠ Disconnect and lockout/tagout input power before connecting input conductors from unit. Follow established procedures regarding the installation and removal of lockout/tagout devices.

⚠ Make input power connections to the welding power source first.

⚠ Always connect green or green/yellow conductor to supply grounding terminal first, and never to a line terminal.

See rating label on unit and check input voltage available at site.

1 Input Power Conductors (Customer Supplied Cord)

Select size and length of conductors using Section 5-4. Conductors must comply with national, state, and local electrical codes. If applicable, use lugs of proper amperage capacity and correct hole size.

Welding Power Source Input Power Connections

2 Strain Relief (Customer Supplied)

Provides filtering on the input line from electrical noise generated by the welding power source.

3 Welding Power Source Grounding Terminal

4 Green Or Green/Yellow Grounding Conductor

Connect green or green/yellow grounding conductor to welding power source grounding terminal first. Connect remaining end to grounding terminal in disconnect device.

5 Welding Power Source Line Terminals

6 Input Conductors L1 (U), L2 (V) And L3 (W)

Connect input conductors L1 (U), L2 (V) and L3 (W) to welding power source line terminals.

Close and secure access door on welding power source.

Disconnect Device Input Power Connections

7 Disconnect Device (switch shown in OFF position)

8 Disconnect Device (Supply) Grounding Terminal

9 Disconnect Device Line Terminals

Connect green or green/yellow grounding conductor to disconnect device grounding terminal first.



Connect input conductors L1 (U), L2 (V) And L3 (W) to disconnect device line terminals.

10 Over-Current Protection


Select type and size of over-current protection using Section 5-4 (fused disconnect switch shown).

Close and secure door on line disconnect device. Follow established lockout/tagout procedures to put unit in service.

5-8. Connecting 3-Phase Input Power For DC 1000/1250 Models



Ref. 800103-C / Ref. 802295



5-9. Connecting 3-Phase Input Power For DC 1000/1250 Models (Continued)



⚠ Installation must meet all National and Local Codes – have only qualified persons make this installation.

⚠ Disconnect and lockout/tagout input power before connecting input conductors from unit. Follow established procedures regarding the installation and removal of lockout/tagout devices.

⚠ Make input power connections to the welding power source first.

⚠ Always connect green or green/yellow conductor to supply grounding terminal first, and never to a line terminal.

See rating label on unit and check input voltage available at site.

1 Input Power Conductors (Customer Supplied Cord)

Select size and length of conductors using Section 5-4. Conductors must comply with national, state, and local electrical codes. If applicable, use lugs of proper amperage capacity and correct hole size.

Welding Power Source Input Power Connections

2 Strain Relief (Customer Supplied)

Route conductors (cord) through strain relief and tighten screws.

3 Machine Grounding Terminal

Connect green or green/yellow grounding conductor to welding power source grounding terminal first.

4 Welding Power Source Line Terminals

5 Input Conductors L1 (U), L2 (V) And L3 (W)

Connect input conductors L1 (U), L2 (V) and L3 (W) to welding power source line terminals.

Close and secure access door on welding power source.

Disconnect Device Input Power Connections

6 Disconnect Device (switch shown in OFF position)

7 Disconnect Device (Supply) Grounding Terminal

Connect green or green/yellow grounding conductor to disconnect device grounding terminal first.

8 Disconnect Device Line Terminals

Connect input conductors L1 (U), L2 (V) And L3 (W) to disconnect device line terminals.

9 Over-Current Protection

Select type and size of over-current protection using Section 5-4 (fused disconnect switch shown).



Close and secure door on line disconnect device. Close and secure door on line disconnect device. Remove lockout/tagout device, and place switch in the On position.

SECTION 6 – SYSTEM CONNECTIONS

6-1. Terminal Strip TE2 and Receptacle RC1 Information

Function	Socket On RC1	Terminal On TE2	Contact Information
Electrical Input Power	A, B	-	24 VAC. Protected by circuit breaker CB2.
	C, D	-	24 VAC common.
Accessory Serial Communication	J	-	+Accessory RS- 485 communication.
	V	-	-Accessory RS- 485 communication.
	Q	-	Accessory serial communication common.
Shield	H	-	Contact E/F shield drain lead.
Power Source Serial Communication	P	-	+Power source RS-485 communication.
	N	-	-Power source RS-485 communication.
	Z	-	Power source serial communication common.
Shield	G	-	Contact H/J shield drain lead.
PS/PS Communication	K	-	Communication link in.
Power Source Synchronization	E	-	Synchronization in.
Volt Sense	W	-	+ Volt sense.
	X	-	Reserved for - volt sense.
Shield	N	-	Contact M/L shield drain lead.
Remote Voltage Sensing	-	N	Voltage sensing signal from Work weld output terminal.
	-	P	Voltage sensing signal from Electrode weld output terminal.
	-	TP	Test point.

- Not Applicable



Ref. 265207-A / 265690-B

⚠ Turn off welding power source before opening access door.

- 1 Access Door
- 2 Remote Receptacle RC1 (Mounted Inside Access Area)
- 3 Terminal Strip TE2
- 4 SubArc Interface
Connect RC1 on SubArc Interface to Remote receptacle RC1 on power source.
- 5 Modbus RTU
For use with optional PLC control.

☞ A DC 650/800 model is shown. Location is the same for DC 1000/1250 models.

6-2. Terminal Strip TE1



265207-A / 261064-A



⚠ Turn off welding power source before opening access door.

1 Access Hole

Remove knockout or cover from access hole and install customer supplied strain relief. Route cable connections through the access hole.

2 12-Pole Terminal Strip

3 Label

Remove and retain screws and open terminal strip panel. Make connections per the label on the panel. Close panel and replace screws.

☞ A DC 650/800 model is shown. Location is the same for DC 1000/1250 models.

Terminal	Functional Information
A, B	10 VDC remote contactor. Connecting terminals A and B will enable output.
C	Remote command reference +10 VDC. Connecting terminals C, D, E will allow remote control.
E	Output command 0 to +10 VDC. Connecting terminals C, D, E will allow remote control.
D	Remote common.
F	Connecting terminals F and D will provide current feedback (1V/100A).
H	Connecting terminals H and D will provide voltage feedback (1V/10A).
M, L	Remote power on/off. Connecting a switch to terminals M and L allow the power source to be remotely turned on or off.

SECTION 7 – MAKING WELD OUTPUT CONNECTIONS

7-1. Weld Output Terminals And Selecting Cables Sizes*

NOTICE – The Total Cable Length in Weld Circuit (see table below) is the combined length of both weld cables. For example, if the power source is 100 ft (30 m) from the workpiece, the total cable length in the weld circuit is 200 ft (2 cables x 100 ft). Use the 200 ft (60 m) column to determine cable size.

Welding Amperes	Weld Cable Size** and Total Cable (Copper) Length in Weld Circuit Not Exceeding***							
	100 ft or Less (30 m)		150 ft (45 m)	200 ft (60 m)	250 ft (70 m)	300 ft (90 m)	350 ft (105 m)	400 ft (120 m)
	10 - 60% Duty Cycle AWG (mm ²)	60 - 100% Duty Cycle AWG (mm ²)	10 - 100% Duty Cycle AWG (mm ²)					
100	4 (20)	4 (20)	4 (20)	3 (30)	2 (35)	1 (50)	1/0 (60)	1/0 (60)
150	3 (30)	3 (30)	2 (35)	1 (50)	1/0 (60)	2/0 (70)	3/0 (95)	3/0 (95)
200	3 (30)	2 (35)	1 (50)	1/0 (60)	2/0 (70)	3/0 (95)	4/0 (120)	4/0 (120)
250	2 (35)	1 (50)	1/0 (60)	2/0 (70)	3/0 (95)	4/0 (120)	2x2/0 (2x70)	2x2/0 (2x70)
300	1 (50)	1/0 (60)	2/0 (70)	3/0 (95)	4/0 (120)	2x2/0 (2x70)	2x3/0 (2x95)	2x3/0 (2x95)
350	1/0 (60)	2/0 (70)	3/0 (95)	4/0 (120)	2x2/0 (2x70)	2x3/0 (2x95)	2x3/0 (2x95)	2x4/0 (2x120)
400	1/0 (60)	2/0 (70)	3/0 (95)	4/0 (120)	2x2/0 (2x70)	2x3/0 (2x95)	2x4/0 (2x120)	2x4/0 (2x120)
500	2/0 (70)	3/0 (95)	4/0 (120)	2x2/0 (2x70)	2x3/0 (2x95)	2x4/0 (2x120)	3x3/0 (3x95)	3x3/0 (3x95)
600	3/0 (95)	4/0 (120)	2x2/0 (2x70)	2x3/0 (2x95)	2x4/0 (2x120)	3x3/0 (3x95)	3x4/0 (3x120)	3x4/0 (3x120)
700	4/0 (120)	2x2/0 (2x70)	2x3/0 (2x95)	2x4/0 (2x120)	3x3/0 (3x95)	3x4/0 (3x120)	3x4/0 (3x120)	3x4/0 (4x120)
800	4/0 (120)	2x2/0 (2x70)	2x3/0 (2x95)	2x4/0 (2x120)	3x4/0 (3x120)	3x4/0 (3x120)	4x4/0 (4x120)	4x4/0 (4x120)
900	2x2/0 (2x70)	2x3/0 (2x95)	2x4/0 (2x120)	3x3/0 (3x95)				
1000	2x2/0 (2x70)	2x3/0 (2x95)	2x4/0 (2x120)	3x3/0 (3x95)				
1250	2x3/0 (2x95)	2x4/0 (2x120)	3x3/0 (3x95)	4x3/0 (4x95)				


* This chart is a general guideline and may not suit all applications. If cable overheats, use next size larger cable.

**Weld cable size (AWG) is based on either a 4 volts or less drop or a current density of at least 300 circular mils per ampere. () = mm² for metric use.

***For distances longer than those shown in this guide, see AWS Fact Sheet No. 39, Welding Cables, available from the American Welding Society at <http://www.aws.org>.

Ref. S-0007-M 2017-08

7-2. Weld Output Terminals



1 Positive (+) Weld Output Terminal
2 Negative (-) Weld Output Terminal

265207-A

output term1 2015-02

Turn off power before connecting to weld output terminals.



Do not use worn, damaged, undersized, or repaired cables.

1 Positive (+) Weld Output Terminal

2 Negative (-) Weld Output Terminal

For welding output terminal connections see Sections 7-4 and 7-5.

7-3. Connecting Weld Output Cables



803778-B

connecting weld output cables 3-2010

3/4 in. (19 mm)

Turn off power before connecting to weld output terminals.

Failure to properly connect weld cables may cause excessive heat and start a fire, or damage your machine.

Do not place anything between weld cable terminal and copper bar. Make sure that the surfaces of the weld cable terminal and copper bar are clean.

- 1 Correct Weld Cable Connection
- 2 Incorrect weld Cable Connection
- 3 Weld Output Terminal
- 4 Supplied Weld Output Terminal Nut

5 Weld Cable Terminal


6 Copper Bar

Remove supplied nut from weld output terminal. Slide weld cable terminal onto weld output terminal and secure with nut so that weld cable terminal is tight against copper bar.

7-4. Basic SubArc (SAW) Welding

☞ Customer must supply the following: power source, power source control cable, wire drive assembly, wire drive extension cable, drive rolls, torch, welding wire, weld cables, remote voltage sense leads, flux hopper, flux hopper extension cable, and flux system for the desired application.

A. Basic SubArc SAW Equipment Connections For DCEP




B. Remote Voltage Sensing Leads Placement Guidelines For A Single Arc (Required)



BAD

Sense lead is affected by weld current.

Due to voltage drops across work piece, arc voltage may be low, causing need for deviation from standard procedures.




BEST

Sense leads are out of the current paths.

Sense leads detect arc voltage accurately.

Best starts, arcs and most reliable results.




Ref. 804108-A


C. Sensing Lead Placement Guidelines For Multiple Arcs




BAD
 Current flow from lead affects trail sense.
 Current flow from trail affects lead sense.
 Neither sense lead picks up the correct work voltage, causing starting and welding arc instability.




BAD
 Lead sense is affected by weld current from lead.
 Trail sense lead is affected by weld current from trail.
 Due to voltage drops across work piece, arc voltage may be low, causing need for deviation from standard procedures.



BEST
 Both sense leads are out of the current paths.
 Both sense leads detect arc voltage accurately.
 No voltage drop between lead and trail sense.
 Best starts, arcs and most reliable results.



D. Basic SubArc SAW Equipment Connections For DCEN



Ref. 254240-A

⚠ Turn off welding power source and weld control before making connections.



☞ Use remote voltage sense leads in all applications.

☞ Suggested size for remote voltage sense wire 12 gauge or larger.

☞ Tie-off and secure electrode-volt sense lead from motor cable when setting up to operate in DCEN.

☞ A DC 650/800 Digital model is shown. Connections are the same for DC 1000/1250 Digital models.

7-5. Typical Connection For CAC-A Process



272583-B

⚠ Turn off welding power source and weld control before making connections.

- 1 DC Power Source
- 2 Electrode Holder (Carbon Arc)

For CAC-A process connect carbon arc cutting torch to positive (+) weld terminal.

- 3 Compressed Air Line
- 4 Work Lead


Connect work lead to negative (-) output terminal.

- 5 Workpiece

7-6. Connecting Multiple Units




Parallel Connections For Digital 650/800 Machines:



254241-A

Parallel Connections For Digital 1000/1250 Machines:



265208-A

⚠ Turn off welding power source and weld control before making connections.

NOTICE – If there are any questions regarding the paralleling procedure, contact the factory before connecting units. Severe damage to units may occur if units are not correctly connected for parallel operation.


To use two or more units with one electrode, make connections as shown.

☞ The first unit controls voltage. All remaining units supply additional current.

☞ Only like power sources can be paralleled.

SECTION 8 – POWER SOURCE OPERATION

8-1. Controls



262962-B

⚠ Turn off welding power source and weld control before making connections.

1 Process Selector Switch

Place switch in position for desired process.

SubArc Mode - For SAW (SubArc) applications.

CC Mode - For gouging applications.

2 Output Control Switch (Contactor)

For weld output, place switch in On position. Switch is disabled when a SubArc Interface is connected to Remote Receptacle RC1 and powered on, or when a PLC has active control through the Modbus RTU connector.

It is disabled if the power source is a following unit in parallel configuration.

3 Output On LED

⚠ Output is on and weld output studs are energized when LED is lit.

⚠ Turn Off power before connecting remote device.

For front panel control of output, place switch in On position. For remote control of output, place switch in Remote position, and connect remote device to RC1. Remote control provides full range of unit output regardless of A/V Adjust control setting. If the output is on before a remote accessory is powered on, the power source will ignore the accessory until the output is turned off.

4 Amperage/Voltage Adjustment Control

When Process Selector switch is in the Constant Current position, turn control clockwise to increase amperage. Read amperage from outer scale of control. Numbers on scale are for reference only. When the Process Selector switch is in the Subarc position, Control can be adjusted while welding.


5 Status/Trouble Light

When a fault occurs, LED flashes a sequence code to identify the fault (see Section 10-1).

6 Power Switch With Indicator Light

SECTION 9 – PLC OPERATION

9-1. Automation Interface Hardware Configuration (PLC Users Only)



⚠ Disconnect and lockout/tagout input power before connecting input conductors from unit. Follow established procedures regarding the installation and removal of lock/out tagout devices.

1 Switch DIP 1

Configure switch DIP 1 on Automation Interface board PC4 to match the network baud rate and parity settings, and set the MODBUS address for this device. (see Tables 9-1 thru 9-3).

Table 9-1. MODBUS Address

DIP1				Address
1	2	3	4	
ON	ON	ON	ON	40
OFF	ON	ON	ON	41
ON	OFF	ON	ON	42
OFF	OFF	ON	ON	43
ON	ON	OFF	ON	44
OFF	ON	OFF	ON	45
ON	OFF	OFF	ON	46
OFF	OFF	OFF	ON	47
ON	ON	ON	OFF	60
OFF	ON	ON	OFF	61
ON	OFF	ON	OFF	62
OFF	OFF	ON	OFF	63
ON	ON	OFF	OFF	64
OFF	ON	OFF	OFF	65
ON	OFF	OFF	OFF	66
OFF	OFF	OFF	OFF	67

☞ Default Setting

Table 9-2. Baud Rate Data

DIP1		Rate
5	6	
ON	ON	9600
OFF	ON	19200
ON	OFF	38400
OFF	OFF	reserved

☞ Default Setting

Table 9-3. Parity Data

DIP1		Parity
7	8	
ON	ON	EVEN
OFF	ON	ODD
ON	OFF	NONE
OFF	OFF	reserved

☞ Default Setting

265207-B

9-2. Connection To PLC

The automation interface uses an RJ45 connector to communicate MODBUS RTU over RS485.

☞ The automation interface is NOT an Ethernet connection!.

The pin connections are as follows:

Table 9-4. Connector Pinout

Function	RJ45 Pin	Circuit
Digital Communication	4	D+
	5	D-
	6	Common
Shield	Case	Shield

9-3. Example Power Source Operation Using A PLC

1	To enable welding control from the Automation Interface, set the "Automation Enable" bit (0x4000) in the Command Flags register (MODBUS Holding Register 101).	4	Set all relevant parameters (MODBUS Holding Registers 102-107) to their desired values. They must be within the minimum and maximum values read in Step 2. Verify the values are correct by reading Input Registers 102-107.	7	Disable weld output by clearing the Output Enable Flag to 0 in the Command Flags register (MODBUS Holding Register 101).			
2	Set desired Weld Mode by writing MODBUS Holding Register 105 using look-up table Table 9-6.	5	Enable weld output by setting the Output Enable Flag to 1 in the Command Flags register (MODBUS Holding Register 101).	8	If there is no communication from the MODBUS master for a period greater than one second, the power source will reset all registers to their default value. Communication can consist of reading or writing.			
3	Obtain Minimum and Maximum values by reading from Input Registers section 300 (See Table 9-8).	6	Voltage & Current Feedback values can be read from Input Registers section 200 (See Table 9-8).	9	It is recommended to continuously poll all welding parameters via the MODBUS master.			

Table 9-5. MODBUS Function Codes

Function	Function Code
Read Input Register	4
Read Holding Register	3
Write Single Register	6
Write Multiple Register	16
Read/Write Multiple Register	23

Table 9-6. MODBUS Holding Registers

Register Address		Register Name	Register Description
PDU	MODBUS		
100	101	Command Flags	See Table 9-7.
101	102	Weld Voltage Command	Voltage command in 0.1V (used for CV & CV+C)
102	103	Weld Current Command	Current command in 1A (used for CC & CV+C)
103	104	Weld Wire Speed	Wire speed in IPM (only an initial guess in CV+C)
104	105	Weld Mode	See Table 9-10.
105	106	Run-In Speed Percentage	Run-in wire speed percentage (%) of weld wire set-point
106	107	Burn Back Time	Time in which power source is on, with wire stopped, in milliseconds.
107	108	Drive Roll Diameter	Diameter in 0.001 in. Only used when RAD 100 is connected

Table 9-7. Command Flags (MODBUS 101)

Flag Name	Bitmask	Description
Output Enable	0x0001	Enable Weld Output
Wire Jog Up	0x0002	Feed Wire Up
Wire Jog Down	0x0004	Feed Wire Down
Flux On	0x0008	Open Flux Valve
Motor CW	0x2000	Motor Direction (Clockwise=1)
Automation Enable	0x4000	Enable Control From PLC
Reset Faults	0xC000	Fault Reset (All Other Bits MUST Be 0)
Reserved	0x0010 - 0x1000	Reserved For Future Use (MUST Be 0)

Table 9-8. Input Registers

Register Address		Register Name	Register Description
PDU	MODBUS		
100	101	Command Flags	Used for holding register verification (see Table 9-6).
101	102	Weld Voltage Command	
102	103	Weld Current Command	
103	104	Weld Wire Speed	
104	105	Weld Mode	
105	106	Run-In Speed Percentage	
106	107	Burn Back Time	
107	108	Drive Roll Diameter	
System Feedback Values			
200	201	Status Flags	See Table 9-9.
201	202	Voltage Feedback	Voltage feedback (volts x 10)
202	203	Current Feedback	Current feedback (amps)
203	204	Help Code	System help code during errors (0 otherwise)
204	205	Wire Feed Speed Feedback	WFS feedback (IPM)
205	206	Program Number	Present active program number
Minimum/Maximum Values (Dependent Upon Power Source, Motor And Weld Mode)			
300	301	Min Voltage	Minimum voltage (0.1V) for MODBUS 102
301	302	Max Voltage	Maximum voltage (0.1V) for MODBUS 102
302	303	Min Current	Minimum current (1A) for MODBUS 103
303	304	Max Current	Maximum current (1A) for MODBUS 103
304	305	Min WFS	Minimum wire feed speed (IPM) for MODBUS 104
305	306	Max WFS	Maximum wire feed speed (IPM) for MODBUS 104
306	307	Min Burnback Time	Minimum burnback time (ms) for MODBUS 107
307	308	Max Burnback Time	Maximum burnback time (ms) for MODBUS 107
308	309	Min Drive Roll Diameter	Minimum roll diameter (0.001 in.) for MODBUS 108
309	310	Max Drive Roll Diameter	Maximum roll diameter (0.001 in.) for MODBUS 108
System Information			
400	401	Power Source Version	High byte – major version # / low byte – minor version #
401	402	Automation Board Version	High byte – major version # / low byte – minor version #
402	403	Motor Board Version	High byte – major version # / low byte – minor version #
403	404	Display Board Version	High byte – major version # / low byte – minor version #

Table 9-9. Status Flags (MODBUS 201)



Flag Name	Bitmask	Description
Valid Arc	0x0001	A valid arc has been detected.
Output On	0x0002	The power source output is on.
Run In	0x0004	The power source is in Run In.
Weld	0x0008	The power source is in the weld state.
Burnback	0x0010	The power source is in the burnback State.
Error	0x8000	The power source is in an Error Condition (read MODBUS Input Register 204).

Table 9-10. Weld Mode Look Up Table

Mode	Balance	Line Input Frequency (Hz)		Weld Mode Code
		60 Hz Line	50 Hz Line	
CV	Electrode Positive	--	--	0x0000
CV+C	Electrode Positive	--	--	0x4000
CC	Electrode Positive	--	--	0x8000

SECTION 10 – MAINTENANCE AND TROUBLESHOOTING

10-1. SubArc System Help Codes

SubArc Interface Digital Help Code	SubArc Power SourceStatus/Trouble Light	Fault	Description
 HELP will display in the upper display, and the code number will display in the lower display.	 Each flash sequence will be followed by a one second pause. The second pause. The sequence will then repeat.		
03	3 Slow	See 30	
04	4 Slow	See 40	
05	5 Slow	Primary Circuit Over Temperature	Indicates unit has overheated. Unit has shutdown to allow fans to lower temperature. Operation will continue after unit is within normal temperature range.
06	6 Slow	See 60	
26	2 Quick, 6 Slow	Button Stuck On System Interface Motor Control	Indicates button is stuck on the lower half of the SubArc Interface upon start up, or Remote Start, Jog Up, or Jog Down is being held low during start up. Fault will clear when button is released.
30	3 Quick	Stuck Contactor On Power Source	Indicates stuck contactor on (Output On switch) the power source. Fault will clear when panel switch is set to remote or contactor is released.
32	3 Quick, 2 Slow	Coolant Flow Error	Indicates coolant input on TB2 in the SubArc Interface is not connected to common on TB2 (see appropriate Interface OM). Check coolant flow and common connections. Ensure sensor being used has a normally-open contact. Sensor is only active if a Strip Drive 100 is connected.
40	4 Quick	Tach Error	Indicates tach error on motor. Check wire feed drive housing and wire spool for obstructions. Make sure motor cable is not routed with weld cable (If inching works properly, noise may be corrupting the tach signal). If this code continues to appear on the display, contact the nearest Factory Authorized Service Agent.
42	4 Quick, 2 Slow	Motor Error	Indicates motor overcurrent error on motor. Check wire feed drive housing and wire spool for obstructions. If this code continues to appear on the display, contact the nearest Factory Authorized Service Agent.

44	4 Quick, 4 Slow	Motor Low Bus	Indicates bus voltage in SubArc Interface is low. 24 VAC from power source may be low if input primary line voltage is too low or, for DC power sources, power source could be incorrectly linked. Increase primary line voltage to at least 90% of specified nominal voltage. Check for correct linking on DC power sources. If this code continues to appear, contact nearest Factory Authorized Service Agent.
45	4 Quick, 5 Slow	Button Stuck On System Interface Digital Display Board	Indicates button is stuck on the digital interface upon power up. Fault will clear when button is released.
48	4 Quick, 8 Slow	Trigger Fault	Indicates an arc was not established with the specified time (lesser of 8 seconds or 4 inches).
56	5 Quick, 6 Slow	Modbus Control Fault	Indicates PLC is enabling weld output, flux, or wire jog on initial communication. Clear all control bits of MODBUS 101 to reset.
60	6 Quick	Memory Card Fault	Indicates unable to read memory card. Faulty memory card or wrong format.
61	6 Quick, 1 Slow	File Read Error	Indicates faulty file on memory card.
62	6 Quick, 2 Slow	File Write Error	Indicates faulty file on memory card.
63	6 Quick, 3 Slow	Invalid File	Indicates an invalid file on memory card. The system was able to read the file; however, the contents of the file were invalid. Remove card or press any button to clear error.
64	6 Quick, 4 Slow	Memory Card Locked	Indicates a save was attempted to a locked card. This refers to the physical switch on the memory card. Unlock the memory card and try again. Try a different memory card. Remove card or press any button to clear error. If this code continues to appear on the display, contact the nearest Factory Authorized Service Agent.
65	6 Quick, 5 Slow	Read Only File	Indicates a save was attempted to a file that has been marked read-only. Check with the appropriate person to see if the attributes are read only for a reason (the attributes can be altered using a PC). Use a different card. Remove card or press any button to clear error.
66	6 Quick, 6 Slow	No Memory Card Detected	Indicates no memory card detected when a memory card operation was attempted. Insert a card or press any button to clear error. Try a different memory card. If this code continues to appear on the display, contact the nearest Factory Authorized Service Agent.
67	6 Quick, 7 Slow	Unsupported Memory Card Format	Indicates the file system is not supported. Memory card size is too small.

71	7 Quick, 1 Slow	Invalid Model Type	If paralleling units, firmware in controlling power source does not match firmware in the following power source. Update firmware in both machines to the latest revision. If code continues to display, contact nearest Factory Authorized Service Agent.
72	7 Quick, 2 Slow	Invalid Motor Type	Indicates resistor is missing or improperly installed in motor cable. Make sure the motor being used is support by this system (see Section 4-5). Check motor to system interface control cable connection and tighten if necessary (See Section 7-4). If this code continues to appear on the display, contact the nearest Factory Authorized Service Agent.
73	7 Quick, 3 Slow	Program Select Error	Indicates an invalid program has been selected using the program select inputs on the terminal strip. The program select is not available because locks are enabled. This error will only occur with program select mode enabled.
92	9 Quick, 2 Slow	Parallel Communication Loss	On trail unit – indicates communication cannot be established with lead unit. On lead unit – indicates communication was lost during welding.
93	9 Quick, 3 Slow	PLC Communication Loss	Indicates communication with PLC was lost during welding.
94	9 Quick, 4 Slow	Automation Interface Communication Loss	Indicates communication with Automation Interface was lost during welding.
95	9 Quick, 5 Slow	Serial Communication Loss	Indicates that the Process Control board lost communication with the Motor Control board in the SubArc Interface.
97	9 Quick, 7 slow	Primary Communication Lost	Power source process control board cannot communicate with the output controller. Power cycle unit. If problem persists, contact the nearest Factory Authorized Service Agent.
98	9 Quick, 8 Slow	Serial Communication Loss	Indicates serial communication was initially made and is now malfunctioning. Check SubArc Interface/power source control cable connection and tighten if necessary. May appear normally during firmware updates. If this code continues to appear on the display, contact the nearest Factory Authorized Service Agent.
99	9 Quick, 9 Slow	Serial Communication Malfunction	Indicates serial communication is malfunctioning. Check SubArc Interface/power source control cable connection and tighten if necessary. May appear normally during firmaware updates. If this code continues to appear on the display, contact the nearest Factory Authorized Service Agent.

10-2. Routine Maintenance

<p>⚠ Disconnect power before maintaining.</p> <p><i>👉 Service equipment more often if used in severe conditions.</i></p>		
Maintenance Schedule	Every 3 Months	Every 6 Months
Cords and Cables	Visually Check condition of cords and cables. Replace damaged cords and cables.	•
Cracked Parts	Replace damaged parts.	•
Labels	Check and Replace labels if damaged.	•
Weld Terminals	Clean weld terminals.	•
Clean Unit	Blow out inside of unit.	•







10-3. Fuse F1

		<p>⚠ Disconnect and lockout/tagout input power before checking or changing fuse. Follow established procedures regarding the installation and removal of lockout/tagout devices.</p> <p>1 Fuse F1 (See Parts List For Rating)</p> <p>Fuse F1 protects control transformer from overload. If F1 opens, weld output and fan motor stops. Replace F1.</p> <p>Close and secure access door.</p>
--	--	--


802295

3/8 in.

10-4. Troubleshooting Table


    				
Trouble		Remedy		
No weld output; unit completely inoperative; power switch light off.		Place line disconnect switch in On position (see Section 5-6 or 5-8).		
		Check for open line fuse(s), and replace if open (see Section 5-6 or 5-8).		
		Check for proper input power connections (see Section 5-6 or 5-8).		
		Check for proper jumper link position (see Section 5-5).		
No weld output; meter switch light on.		Check fuse F1, and replace if necessary (see Section 10-3).		
		Unit overheated. Allow unit to cool with fan On (see Section 4-8)		
		If using remote control, place Output (Contactor) switch in Remote 14 position, and connect remote control (see Sections 6-1 and 8-1). If remote is not being used, place switch in On position (see Section 8-1).		
No weld output; power switch light on; fan off.		Check, repair, or replace remote control.		
		Check for proper input power connections (see Section 5-6 or 5-8).		
		Check for open line fuse(s), and replace if open, or reset circuit breaker (see Section 5-6 or 5-8).		
Limited weld output and low open-circuit voltage.		Turn power switch off then back on. If no output condition remains, have Factory Authorized Service agent check SCR's.		
		Check position of Remote Amperage/Voltage Control switch (see Section 8-1).		
		Check for open line fuse(s), and replace if open (see Section 5-6 or 5-8).		
		Check for proper input power connections (see Section 5-6 or 5-8).		
		Check for proper jumper link position (see Section 5-5).		
Unit provides only maximum or minimum weld output.		Clean and tighten all weld output connections.		
		Check position of Remote Amperage/Voltage Control switch (see Section 8-1).		
Erratic or improper weld output.		Have Factory Authorized Service Agent check control board PC1 and hall device HD1.		
		Use proper size and type of weld cable (see Section 7-1).		
		Clean and tighten all weld connections.		
		Check wire drive installation according to Owner's Manual.		
No 24 volts AC output at Remote receptacle RC1		Have Factory Authorized Service Agent check control board PC1 and hall device HD1.		
		Reset supplementary protector CB2.		
Fan not operating.  <i>Fan only operates when cooling is necessary.</i>		Check for and remove anything blocking fan movement.		
		Have Factory Authorized Service Agent check fan motor.		



SECTION 11 – ELECTRICAL DIAGRAMS



 ELECTRIC SHOCK HAZARD	WARNING
	<ul style="list-style-type: none"> • Do not touch live electrical parts. • Disconnect input power or stop engine before servicing. • Do not operate with covers removed. • Have only qualified persons install, use, or service this unit.


Figure 11-1. Circuit Diagram For DC 650/800 Models Eff. w/ME21002G





	WARNING
	<ul style="list-style-type: none"> Do not touch live electrical parts. Disconnect input power or stop engine before servicing. Do not operate with covers removed. Have only qualified persons install, use, or service this unit.
ELECTRIC SHOCK HAZARD	

Figure 11-2. Circuit Diagram For DC 1000/1250 Models Eff. w/ME21002G



262521-F

Owner's Record

Please complete and retain with your personal records.

Model Name _____ Serial/Style Number _____

Purchase Date _____ (Date which equipment was delivered to original customer.) _____

Distributor _____

Address _____

City _____

State _____ Zip _____

For Service

Contact a *DISTRIBUTOR* or *SERVICE AGENCY* near you.

Always provide Model Name and Serial/Style Number.

Contact your Distributor for:

Welding Supplies and Consumables

Options and Accessories

Personal Protective Equipment (PPE)

Service and Repair Replacement Parts

Training (Schools, Videos, Books)

Welding Process Handbooks

To locate a Distributor or Service Agency visit
www.millerwelds.com or call 1-800-4-A-Miller

Contact the Delivering Carrier to:

File a claim for loss or damage during shipment.

For assistance in filing or settling claims, contact your distributor and/or equipment manufacturer's Transportation Department.

Miller Electric Mfg. LLC

An Illinois Tool Works Company
1635 West Spencer Street
Appleton, WI 54914 USA

International Headquarters—USA

USA Phone: 920-735-4505
USA & Canada FAX: 920-735-4134
International FAX: 920-735-4125

For International Locations Visit
www.MillerWelds.com

