


TRANSMISSION NOISE




TRANSMISSION OVERHEATING



LOW POWER: ONE OR BOTH DIRECTIONS



WILL NOT OPERATE IN ONE OR BOTH DIRECTIONS



CREEPS IN NEUTRAL

